

CK-2321

BLUE MTN TWO 2.2km

2017 Inspection

CBR iPad Offline Ver 0.26



CBR Data

Latitude	Longitude
49°14'28.7"	-122°28'45.7"
Crossing Name	Martyn Creek 2
FSR #	5913
Branch #	2
Road Name	BLUE MTN TWO
User km	2.2
Current Load Rating (tonnes)	
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	8
Deck Width (m)	99

Updated Data

Latitude	Longitude
49°14'28.72"	-122°28'45.43"
HD Diff. (m)	5.5
Accuracy (m)	5
Others	
Gravel	
Other	
Other	
0	
0	
6.0	

Inspection

Date of Inspection 2017-07-20 9:21:52 AM

Inspector Name Tyson Miller

Inspector Comments

2 - 700mm heavy steel wall pipes
Modified ford

Recommended Next Inspection Year - Inspect with road inspections

Inspection Company MFLNRO

P.Eng Comments

Modified ford, inspect with regular road inspections. Clean inlet. BCL-625 or 64 tonnes.



30/08/2017

P.Eng Seal

CK-2321

BLUE MTN TWO 2.2km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition NA

Posted Load Rating Not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection



Approach from Left Bank when facing downstream



Inlet



Walk bridge



Approach from Right Bank when facing downstream

CK-2321

BLUE MTN TWO 2.2km

2017 Inspection



Outlet



Martin Creek - East Fork sign