121°15'0"W

121°10'0"W

50°40'0"N

N

Breach Berm

MG-1-1

39% 20m

Fence Damage

MG-1-1

Barnes Lake

H2

K21849

Barnes Lake

Recontour

Cross Ditch - Install

MG-1-6

Cross Ditch - Install

Safety Zone

MG-1-6

Bunched Fd Burnt

RD-1-4

Safety Zone

Placemark 8

RD-1-2

Zone 4

MG-4-32

RD-4-5

MG-4-32

MG-4-32

MG-4-32

MG-4-32

MG-1-7

40% 30m

MG-1-7

MG-1-7

H3

H16

MG-1-7

RD-1-6

MG-1-7

50% 10m

40% 20m

Safety Zone

MS 462 C-M VW

Zone 1

Fence Damage

38% 20m

MG-1-9

MG-1-10

MG-1-10

Safety Zone

100m

Recontour

MG-1-8

MG-1-10

35% 50m

MG-1-9

Bunched Fd

MG-1-10

Restore Draw

46% 10m

42% 15m

MG-1-10

MG-1-10

Safe Zone

Restore Draw

MG-1-10

Pile And Burn Slash Here

Stream Crossing No Machine Or Atv Access

Safety Zone

MG-1-10

Decked Wood

MG-1-10

Needs Repair

Safety Zone

MG-1-11

RD-1-8

Stream Crossing

MG-1-11

MG-1-11

MG-1-12

Fuel Hazard

Bunched Wood

RD-2-2

40% 20m

Fuel Hazard

47% 30m

45% 20m

45% 20m

Zone 2

44% 20m

Critical Site Rehab Draw

MG-2-7

46% 50m

MG-2-8

MG-2-8

38% 15m

MG-2-8

MG-2-8

Restore Draw

MG-2-8

Safety Zone

Stream Crossing

Safety Zone

MG-2-8

Restore Draw

Restore Draw

Critical Site

MG-2-7

MG-2-5

Restore Draw

MG-2-7

Restore Draw

Critical Site

Decked Wood

Glossy

Decked Wood

GLOSSY MTN

Document Path: Y:\Fire\Season\Work\2021\Fuels\pyro\K21849\K21849_Rehab_Sheet1.mxd

121°15'0"W

121°10'0"W

50°40'0"N

Tremont Creek

K21849

REHAB MAP

B1

Map Date: June 10, 2022

Perimeter Date:2021-08-20
Hectares: 62523.6HA

2 OPS Point [PTType]

PTType

- OPS Cleared Area
- Water Source
- Breach Berm (BB)
- Cross Ditch - Install (CDI)
- Decked Wood (DW)
- Ditch - Clean/Repair (CD)
- Fence Damage - Point (FD)
- Recontour (RC)
- Restore Draw (RD)
- Safety Zone (SZ)
- Slash / Burn Pile / Hazard (SBP)
- Steep Slope >35% (SS)
- Stream Crossing (SC)
- Unassigned
- Unique Point (UP)

Other Rehab Treatment Type

- Pull Back (PB)
- Hazard (H)
- Fireguard Machine Completed
- Road - Modified Existing
- Other
- Unassigned
- Rehab - Requires Field Verification
- Rehab - Requires Field Verification
- Fire Perimeter

- Utb Grid
- Rehab Work Zone Boundary
- Trail
- Trails
- Highway
- Forest Service Road
- Road Permit
- Highway
- Road
- Transmission Lines
- Transmission Line
- Transmission Line
- Airstrip or Other Facility
- Mountain
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Reservoir
- Wetland
- Failing or Gullied Terrain
- Campsite
- InterpretiveForestRecreationReserve
- Transmission Lines
- Transmission Line
- Transmission Line
- Radio Tower
- Groundwater Well
- Dam
- Archaeological Site
- Water Development
- Fence
- Stock Trail
- Aquatic
- Fish - Observed
- Lake
- Lake - Intermittent
- Reservoir
- Indian Reserve
- Private
- Federal
- Municipal
- Private
- Crown Municipal
- Crown Federal

Index Map



This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Fire perimeters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems on a daily basis. The accuracy of this data is limited to the current fire situation, and therefore should only be used for general reference.

Wildfire data from the incident is updated when practicable and the occurrence of individual fire updates will vary. The information is intended for general reference purposes only and may not be accurate or complete because fires are dynamic and circumstances may change quickly. The levels of current fire activity within the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created by: Jhamilton

Ministry of Forests, Lands, Natural Resource Operations and Rural Development