121°5'0"W

121°0'0"W

51°40'30"N

N

MG-2-10

MG-2-8

Woods Creek

20 Logs

Clean Stream Below Rd

Bunched Sx Along Rd

Bladder

Tremont

Safety Zone

Restore Draw Placemark 24

MG-2-12

Restore Draw

Restore Draw

35% 15m

Restore Draw

RD-2-99

Cross Ditch - Install

57% 10m

Restore Draw

Cross Ditch Install

Cross Ditch - Install Zone 2

Fence Damage

MG-2-13

MG-2-12

MG-2-12

Placemark 15

Bunched Pine

MG-2-11

Placemark 54

MG-2-11

MG-2-11

Cross Ditch - Install

Restore Draw

MG-2-14

Placemark 50

Restore Draw

Placemark 47

RD-2-98

Placemark 48

MG-2-15

Placemark 41

H15

MG-2-15

Grass Seed Only

MG-2-16

MG-2-17

MG-2-17

Restore Draw

MG-2-18

Crushed Culvert

MG-2-19

MG-2-18

RD-2-99

Fairly Rocky No Drainages One Steep Section

40 + Short Pitch 20m Rocky

RD-2-99

MG-2-18

MG-2-18

46% 20m

MG-2-18

39% 15m

Restore Draw

RD

Restore Draw

Restore Draw

Stream Crossing

MG-2-20

Critical Site

Guard Here Map With Image

MG-2-98

Fence

Fence

MG-2-2

AD14 Helispot

North Dozer Guard Parking

Possible Water Source

AD14

MG-3-1

Stream Crossing

Bunched Sx

Hand Guard

Fisher Creek

MG-3-1

Zone 3

First Aid

MS 462 C-M VW

CINDER HILL

FORGE MTN

51°40'30"N

121°5'0"W

121°0'0"W

Document Path: Y:\Fire\Seasonal\Work\2021\Fuels\pyp\KEM\21849\21849_Rehab_50x66L.mxd

Tremont Creek

K21849

REHAB MAP

C2

Map Date: June 10, 2022

Perimeter Date:2021-08-20
Hectares: 62523.6HA

2 OPS Point [PTType]


PTType

- OPS Cleared Area
- Water Source
- Cross Ditch - Install (CDI)
- Cross Ditch - Repair (CDR)
- Culvert - Clean/Repair Culvert (CC)
- Dirckred Wood (DW)
- Fence Damage - Point (FD)
- Other Rehab Treatment Type
- Rimbrm Draw (RD)
- Safety Zone (SZ)
- Staging Area (SA)
- Steep Slope >35% (SS)
- Stream Crossing (SC)
- No Treatment - Point (NA)
- Unassigned
- Unique Point (UP)
- Dry Seed (DS)

- Other Rehab Treatment Type
- Pull Back (PB)
- Firequest Manual Completed
- Firequest Machine Completed
- Road - Modified Existing
- Rehab - Requires Field Verification
- Rehab - Requires Field Verification
- Fire Perimeter

- 10k Grid
- Rehab Work Zone Boundary
- Trail
- Trail
- Highway
- Forest Service Road
- Road Permit
- Highway
- Road
- Transmission Lines
- Transmission Line
- Mountain
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Failing or Gullied Terrain
- Unstable Terrain
- Potentially Unstable Terrain
- Transmission Lines
- Transmission Line
- Groundwater Well
- Dam
- Archaeological Site
- Fence
- Fish - Observed
- Lake
- Lake - Intermittent
- Private
- Mixed Ownership
- Private

Index Map



This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Fire perimeters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems on a daily basis. The accuracy of the data is limited to the current fire situation, and therefore should only be used for general reference.

Wildfire data from the incident is updated when practicable and the occurrence of individual fire updates will vary. The information is intended for general reference purposes only and the status of wildfires and fire/areas fires are dynamic and circumstances may change quickly. The levels of current fire activity within the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created by: jmorrison

Ministry of Forests, Lands, Natural Resource Operations and Rural Development