Tremont Creek

K21849

REHAB MAP

Zone 5 - B1

Map Date: February 21, 2022

Perimeter Date: 2021-08-20
Hectares: 62523.6HA

121°0'0"W

120°55'0"W

50°40'0"N

MT FEHR

MS 462 C-M VW

Safety Zone
Steep Slope
Stream Crossing
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Safety Zone
Cross Ditch Repair
Cross Ditch Repair
Cross Ditch Repair
Cross Ditch Repair
Cross Ditch Repair
Steep Slope
Cross Ditch Repair
Restore Draw
Safety Zone
Steep Slope
Cross Ditch - Repair
Cross Ditch - Repair
Cross Ditch - Repair
Cross Ditch - Repair
Cross Ditch - Repair
Safety Zone
Short Pitch Of 40%
Safety Zone
Fence damage
Steep Slope
Fence damage
Stream Crossing
Safety Zone
Slope Rock 35% 20 M
Gulley
Slope Rock 35% 20 M
Track 24
40 + Short Pitch 20m Rocky
Crushed Culvert
Clear Cross Ditch
40 + Short Pitch 20m Rocky
Restore Draw
RD
Restore Draw
Restore Draw
Track 25
Track 26
46% 20m
Track 25
35% 15m
Critical Site
Stream Crossing
Restore Draw
Guard Here Map With Image
Fence
Fence
Track 76
Restore Draw
Stream Crossing
Track 75
Safety Zone
43%12m
48%10m
Stream Crossing
45%10m
Track 74
Safety Zone
Safety Zone
Safety Zone