120°50'0"W

120°45'0"W

50°30'0"N

50°25'0"N

N

Tremont Creek

K21849

REHAB MAP

Zone 6 - C1

Map Date: February 21, 2022


Perimeter Date: 2021-08-20
Hectares: 62523.6HA

2 QPS Point [PTType]
PTType

- QPS Cleared Area
- Water Source
- Hazard
- Value
- Cross Ditch - Install (CDI)
- Decked Wood (DW)
- Fence Damage - Point (FD)
- Fence No Damaged - Point (FND)
- Other Rehab Treatment Type
- Pull Back (PB)
- Restore Draw (RD)
- Safety Zone (SZ)
- Steep Slope >30% (SS)
- Stream Crossing (SC)
- Unassigned
- Unique Point (UP)
- Other Rehab Treatment Type
- Pull Back (PB)
- Frequent Machine Completed
- Road - Modified Existing
- Rehab - Requires Field Verification
- Rehab - Requires Field Verification
- Fire Perimeter

- Trail
- Trail
- Trail
- Trails
- Forest Service Road
- Road Permit
- Main Road
- Road
- Pipeline
- Pipeline
- Pipeline
- Transmission Lines
- Transmission Line
- Transmission Line
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Freshwater
- Pipeline
- Pipeline
- Pipeline
- Felling or Gullied Terrain
- Unstable Terrain
- Potentially Unstable Terrain
- Campsite
- Day Use
- O&G Facility
- Pipeline
- Pipeline
- Transmission Lines
- Transmission Line
- Transmission Line
- Weather Station
- Weather Station
- Groundwater Well
- Dam
- Archaeological Site
- Legacy Archaeological Site
- Water Development
- Fence
- Stock Trail
- Aquatic
- Fish - Observed
- Lake
- Lake - Intermittent
- BC Park, Protected Area, Eco Reserve
- Private
- Crown Agency
- Private

Index Map



This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Rehab perimeters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems on a daily basis. This information is intended for use for the current fire situation, and therefore should only be used for reference purposes.

Wildfire data from the incident is updated when information is received, however staff changes and updates will occur. The information is intended for general reference purposes only and should not be used as the authoritative data set. Users are responsible to check change quarks. The levels of current fire activity within the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created by: jcarrasco

Ministry of Forests, Lands, Natural Resource Operations and Rural Development
BC Wildfire Service

Decked Wood
Safety Zone
Should Cross Ditch
Restore Draw
Track 60
Decked Wood
Track 93
Decked Wood
Decked Wood
Ground Penalties Road Prep Pull Back Guard
Stream Crossing
Track 62
Track 94
Fence No Damage
Road Repairs
AO18 Helispot
Stream Crossing
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Fence No Damage
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Fence Damage
Restore Draw
Steep Slope
Leighton North
Leighton
Tunkwa Lake
TUNKWA PARK
40% 10m
26% 10m
Track 65
Track 63
Stream Crossing
Stream Crossing
Track 63
Track 64
Track 64
Div. A-Tunkwa
Telus 6
MS 462 C-M VW
Bridge Out
Stream Crossing needs rehab
Corduroy
Decked Wood
Pull Back Berm
Pull Back Berm

Document Path: Y:\Fire\Seasons\wfs2021\work\zone6\C1\K21849\21849_Rehab_Sheet6L.mxd