121°0'0"W

120°55'0"W

50°40'0"N

Tremont Creek

K21849

REHAB MAP

Zone 4 - B2

Map Date: February 21, 2022

Perimeter Date: 2021-08-20
Hectares: 62623.6HA

2 OPS Point [PTType]

PTType

- OPS Cleared Area
- Water Source
- Cattle Guard No Damage (CGND)
- Cross Ditch - Install (CDI)
- Cross Ditch - Repair (CDR)
- Culvert - Clean/Repair Culvert (CC)
- Decked Wood (DW)
- Fence Damage - Point (FD)
- Fence No Damaged - Point (FND)
- Other Rehab Treatment Type
- Restore Draw (RD)
- Safety Zone (SZ)
- Steep Slope >35% (SS)
- Stream Crossing (SC)
- Sump (SP)
- No Treatment - Point (NA)
- Unassigned
- Unique Point (UP)
- Other Rehab Treatment Type
- Pull Back (PB)
- Frequent Machine Completed
- Road - Modified Existing
- Unassigned
- Rehab - Requires Field Verification
- Rehab - Requires Field Verification
- Fire Perimeter

- BC Park, Protected Area, Eco Reserve
- Trail
- Forest Service Road
- Road Permit
- Road
- Transmission Lines
- Transmission Line
- Mountain
- Stream
- Stream - Intermittent
- Lakes
- Lake - Intermittent
- Wetland
- Freshwater
- Lakes
- Lake - Intermittent

Index Map

This map may contain CONFIDENTIAL information; for INTERNAL use only

Disclaimer:
Rehab parameters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems on a daily basis. The data is provided for the purpose of the current fire situation, and therefore should only be used for reference purposes.

Wildfire data from the incident is updated when practicable and the occurrence of individual fire updates may vary. The data provided is for internal use and planning purposes only and should not be relied on as accurate. Fire perimeters are subject to change as the fire's status change quickly. The levels of control for activity within the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created By: jcamben

Ministry of Forests, Lands, Natural Resource Operations and Rural Development
BC Wildfire Service

MT FEHR

MS 462 G-M VW

Machine Guard
Bunched Wood Along Guard
Stream Crossing
Restore Draw
Fence Damage
Fence No Damage
Decked Wood
Safety Zone
Cross Ditch - Install
Steep Slope
Pull Back
Machine Guard
Cattle Guard No Damage
Track 48
Track 47
Track 46
Cross Ditch - Repair
Access to decked Wood
Track 24
Slope Rock 35% 20 M
Gullies
Track 42
Sperm Lake
Fence Damaged
Short Pitch Of 40%
Fence damage
Crushed Culvert
Culvert Cross Ditch
40 + Short Pitch 20m Rocky
Restore Draw
Track 42
Stream Crossing
Cross Ditch