120°50'0"W

120°45'0"W

50°40'0"N

N

Tremont Creek

K21849

REHAB MAP

Zone 5 - B2

Map Date: February 21, 2022

Perimeter Date: 2021-08-20
Hectares: 62523.6HA

MT ANNE

MT DURAND

Safety Zone
Steep Slope
Cross Ditch - Install
Enbridge Vent
Steep Slope
Steep Slope
Decked Wood
Decked Wood
Steep Slope
Steep Slope
Decked - Decked Wood
Decked Wood
Cattleguard - No Damage
Berm to South
Stream Crossing
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
High Berm
Steep Slope
Steep Slope
Safety Zone
Decked Wood
Fence No Damage
Safety Zone
Should Cross Ditch
Restore Draw
Track 60
Decked Wood
Track 93
Decked Wood
Decked Wood
Road Repairs
AD38 Helispot
Stream Crossing
Track 93
Tunkwa Lake
49% 10m
36% 10m
Track 65
Div. A Tunkwa
Telus 6
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope
Steep Slope