Elephant Hill - K20637 Rehab Map

MAP G1

Perimeter Date: 2017/09/18
Fire Size: 192016 ha

F1 F2
G1 G2
H1 H2

OGMA (Legal)
West Fraser Mills Ltd. Block
Stream_Class_Gua...
Breach Berm (BB)
Slash/Burn Pile (BP)
Clean/Repair Culvert (CC)
Cross Ditch (X)
Other Damage (D)

Decked Wood (DW)
Pull Back (PB)
Restore Draw (RD)
Steep Slope (SS)
Stream Crossing (SC)
Unique Point (UP)
No Treatment (NA)
Fence Damage (FD)
Fence No Damage (FND)

Gate Damage (GD)
Staging Area/Safety Zone (SA)
Roads Tenured with Obligations (RT)
Roads Non-Status with Obligations (RNS)
Pull Back (PB)
Steep Slopes (SS)
No Treatment - Line (NA)

Completed Machine Line (MG)
Road - Modified Existing (RM)
Road - Heavily Used (RHU)
Machine Trail (TR)
Water - Pipeline
Divisions
Private Land Impacted by Guard

FirePolygon
Cattleguard (Range Improvement)
Corral (Range Improvement)
Crossing (Range Improvement)
Gate (Range Improvement)
Water Development (Range Improvement)

Fence (Range Improvement)
Contour - 100m
Contour - 20m
Trail
Transmission Line
Transmission Line
Stream
Stream - Intermittent
Lake

Lake - Intermittent
Wetland
Waste Remediation Site
Cutblock - Historical
Cutblock - Active
Cutblock - Planned
Cutblock - Historical
Archaeological Sites
Private Land

Lake

Disclaimer:
This map is intended for general public information only. Best efforts have been made to provide the most accurate fire information at the time of creation of this map. However, fires are dynamic, and the information shown on the map may no longer reflect the most current fire situation. Accordingly, this map only should be used for reference purposes.



Data Sources and Notes

0 100 200 400 600
Meters
1:10,000

BRITISH COLUMBIA

BC Wildfire Service
Ministry of Forest, Lands, Natural Resource Operations and Rural Development

Filename: **K20637_Rehab_10K_36x48P**
Projection: **NAD 1983 BC Environment Albers**
Datum: **North American 1983**
Date/Time Created/Revised: **Apr 10, 2018 0254**
Created by: **klnorthc**

Path: Y:\FireSeasonWork\2017\Kamloops\K2\K20637\MXD\Rehab\K20637_Rehab_10K_36x48P.mxd