




Elephant Hill - K20637

Rehab Map

MAP H2

Perimeter Date: 2017/09/18

Fire Size: 192016 ha

G1 G2 G3

H1 H2 H3

I2 I3

OGMA (Legal)

WHAS

West Fraser Mills Ltd. Block

Stream\_Class\_Gua...

Priority Value (point)

Breach Berm (BB)

Clean Ditch (CD)

Cross Ditch (X)

Decked Wood (DW)

Restore Draw (RD)

Steep Slope (SS)

Stream Crossing (SC)

Water Bar (WB)

Unique Point (UP)

Fence Damage (FD)

Gate Damage (GD)

Gate No Damage (GND)

Staging Area/Safety Zone (SA)

Roads Non-Status with Obligations (RNS)

Pull Back (PB)

Steep Slopes (SS)

Completed Machine Line (MG)

Completed Handline (HG)

Road - Modified Existing (RM)

Point of Diversion

Water - Pipeline

Divisions

Private Land Impacted by Guard

FirePolygon

Cattleguard (Range Improvement)

Corral (Range Improvement)

Water Development (Range Improvement)

Fence (Range Improvement)

Contour - 100m

Contour - 20m

Indian Reserve

Transmission Line

Transmission Line

Transmission Line

Community Watersheds

Woodlot Sched A

Woodlot Sched B

Stream

Stream - Intermittent

Lake

Lake - Intermittent

Wetland

Freshwater

Cutblock - Historical

Cutblock - Active

Cutblock - Historical

Archaeological Sites

Historic Places

Historic Places

Private Land

Lake

First Nation Reserve

0 100 200 400 600

Meters

1:10,000

BC Wildlife Service

Ministry of Forest, Lands, Natural Resource Operations and Rural Development

Filename: K20637\_Rehab\_10K\_36x48P

Projection: NAD 1983 BC Environment Albers

Datum: North American 1983

Date/Time Created/Revised: Apr 16, 2018 0620

Created by: Klnorthic

Disclaimer:

This map is intended for general public information only. Best efforts have been made to provide the most accurate fire information at the time of creation of this map. However, this is dynamic, and the information shown on this map may no longer reflect the most current fire situation. Accordingly, this map only should be used for reference purposes.

Path: Y:\FireSession\W04\2017\K20637\K20637\Map\Rehab\K20637\_Rehab\_10K\_36x48P.mxd