

CHELASLIE RIVER BRIDGE: RO4049-01: STATION 19+200:
 DOWNCHAIN (LOWCHAIN) SUBSTRUCTURE: PILE ABUTEMENT;
 SUMMARY OF MONITORING MEASUREMENTS TAKEN:

DATE	DOWNSTREAM	UPSTREAM
MAY 6, 2003	2 5/8 inches	2 1/4 inches
OCTOBER 16, 2003	2 1/4 inches	2 1/2 inches
APRIL 19, 2004	2 5/8 inches	2 1/4 inches
MAY 31, 2004	2 5/8 inches	2 1/4 inches
AUGUST 17, 2004	2 11/16 inches	2 3/8 inches
SEPTEMBER 8, 2004	2 11/16 inches	2 3/8 inches
OCTOBER 12, 2004	2 5/8 inches	2 3/8 inches
NOVEMBER 18, 2004	2 5/8 inches	2 3/8 inches
JANUARY 20, 2005	2 1/2 inches	2 1/8 inches
FEBRUARY 14, 2005	2 1/2 inches	2 1/8 inches
MAY 3, 2005	2 5/8 inches	2 3/8 inches
MAY 25, 2006	2 3/4 inches	2 3/8 inches
SEPT 19, 2006	2 3/4 inches	2 3/8 inches
MAY 4, 2007	2 3/4 inches	2 3/8 inches
JUNE 8, 2007	High water could not get readings	
OCT 29, 2007	2 3/4 inches	2 9/16 inches
JULY 15, 2009	2 7/8 inches	2 5/8 inches
MAY 19, 2010	2 7/8 inches	- not able to measure - high water

CHELASLIE RIVER BRIDGE: RO4049-01: STATION 19+200:
 DOWNCHAIN (LOWCHAIN) SUBSTRUCTURE: PILE ABUTEMENT;
 SUMMARY OF MONITORING MEASUREMENTS TAKEN:

DATE	DOWNSTREAM	UPSTREAM
MAY 6,2003	2 5/8 inches	2 1/4 inches
OCTOBER 16,2003	2 1/4 inches	2 1/2 inches
APRIL 19,2004	2 5/8 inches	2 1/4 inches
MAY 31,2004	2 5/8 inches	2 1/4 inches
AUGUST 17,2004	2 11/16 inches	2 3/8 inches
SEPTEMBER 8,2004	2 11/16 inches	2 3/8 inches
OCTOBER 12,2004	2 5/8 inches	2 3/8 inches
NOVEMBER 18,2004	2 5/8 inches	2 3/8 inches
JANUARY 20,2005	2 1/2 inches	2 1/8 inches
FEBRUARY 14,2005	2 1/2 inches	2 1/8 inches
MAY 3,2005	2 5/8 inches	2 3/8 inches
MAY 25,2006	2 3/4 inches	2 3/8 inches
SEPT 19,2006	2 3/4 inches	2 3/8 inches
MAY 4,2007	2 3/4 inches	2 3/8 inches
JUNE 8,2007	High water could not get readings	
OCT 29,2007	2 3/4 inches	2 9/16 inches

CHELASLIE RIVER BRIDGE: RO4049-01: STATION 19+200:
DOWNCHAIN (LOWCHAIN) SUBSTRUCTURE: PILE ABUTEMENT;
SUMMARY OF MONITORING MEASUREMENTS TAKEN:

[illegible]