

Post-wildfire Natural Hazards Risk Analysis - Screening, 26 August 2008

Fire Year	Fire Number	Geographic	Latitude	Longitude	Date, Discovery	Size, Current	Remarks for risk assessment
2008	N50245	2 Km South of Edgewood	49 45.932	118 08.436	2008-07-17 13:46	385	Entirely south of developed area; appears to be no resources at risk.
2008	N70268	Woodbury Creek	49 48.180	116 55.260	2008-07-18 16:22	55	FSR accessing Kokanee Glacier Park is below fire
2008	N10313	Newgate	49 04.900	115 44.212 (should be 115 13 ?)	2008-07-21 17:30	35.1	Appears to be undeveloped crown land, but photo shows cabins? (Coordinates in database are wrong.)
2008	N10318	South of Lakit rd	49 39.955	115 39.930	2008-07-22 11:27	329	Burned hillslopes above Hwy 93, part crown, part private.
2008	N10647	perry creek	49 34.222	116 02.157	2008-08-17 14:43	170	May be private land and improvements downstream?

Summary of risk analysis (draft, 6 Oct 2008)

Fire Year	Fire Number	Geographic	Resources at risk	Hazard	Consequence	Risk	Remarks
2008	N50245	2 Km South of Edgewood	none				Inspected from the air; confirmed no development below fire; no further analysis done.
2008	N70268	Woodbury Creek	Woodbury FSR; public access to Kokanee Glacier Park	M	L	L	Low risk to the travelling public; possible moderate risk to small creek crossings on the road. Road inspected in the field by P Jordan, 30 Sept 2008.
2008	N10313	Newgate	none known				no further analysis done
2008	N10318	South of Lakit rd	Highway 93, CPR rail line	L	M	L	Low risk to highway and railway due to gentle slopes and generally moderate burn severity. Field inspection by M Curran, 24 Aug 2008. Rehab issues discussed in a separate e-mail.
2008	N10647	perry creek	none known				no further analysis done