Tag: 15

Information Source:

Debris Torrents Golden Area, Boyer, Dwain (WLAP Report# 755); Misc. Stream Channel Restoration Upper Columbia River Valley, Zackodnik; Oxland (WLAP Report# 785); Terrain Stability Inventory Alluvial And Debris Torrent Fans Kootenay Region, Klohn-Crippen (WLAP Report# 1020); File Report: May 16, 1990 Inspection, Boyer Dwain (WLAP Report# 1519); File Report: Birchland/ Drybed Creeks- Site Inspection, Boyer, Dwain (WLAP Report# 1520)

Information Date:

19/06/2000; 02/09/1976; 23/02/1998; 16/05/1990; 25/05/1990

Comments:

Massive debris flow occurred in 1982, damaging property and blocking highway. Large berms pushed up by MOT in 1982 are not monitored or maintained. CPR has to regularly clear channel to maintain channel under their bridge. Due to high flooding and erosion hazard WLAP has refused consent to approve subdivisions in polygon.

For more information refer to WLAP complaint files 55.5016011, 55.501036, 55.501046, 55.501078 and 1986 air photos.

WLAP Flood photos on file: see files # 55.5016063, 55.5016046, and 55.5016021.