



March 18TH, 2021

Notice Type: Road or Forest Closures/Restrictions
Issuing Office: Okanagan-Columbia Timber Sales Office
Title: Forest Service Road Deactivation and Closures - Okanagan-Columbia Business Area

Notice – Forest Service Road Deactivation and Closure

Under Section 121 (9) of the Forest Act, Branches and partial Branches of several Forest Service Roads are in the process of being discontinued and permanently closed.

See the attachment for the list affected FSRs and Maps are available for download at the following FTP address:

<https://www.for.gov.bc.ca/ftp/TOC/external!/publish/Notice%20FSR%20Deactivation%20and%20Closure/>

These roads were built or utilized by BCTS and now are surplus to industrial needs. The Ministry does not have the ability to maintain surplus roads. If any stakeholders identify roads that should remain open and be maintained, the ministry can reassign the maintenance obligations to them through the issuance of an applicable tenure. **Roads which are not reassigned to new tenures will be scheduled for permanent deactivation.**

The Ministry is sending this notice to provide an opportunity for stakeholders to review the surplus roads and identify any additional roads that should remain open and maintained for industrial activity.

If you have any comments or questions concerning these closures please contact Kevin Hodder at (250) 309-7899 or email Alex.Soukup@gov.bc.ca

ROAD_NAME	ROPA_OPERATING_AREA
C 0604.03 (BR 27.1)	X56
C 10236.02 (DAYDREAM - BR 4.1)	X55
C 3461.02 (DONALD-WISEMAN)	X07
C 3461.03 (DONALD-CIRQUE)	X07
C 3461.04 (DONALD - CIRQUE BR 0.9)	X07
C 3461.06 (DONALD BR 13.9A)	X07
C 3461.07 (DONALD BR 13.9B)	X07
C 3461.08 (DONALD BR 12.4)	X07
C 4170.04 (ICE)	ICR
C 4170.05 (ICE BR 38)	ICR
C 4170.07 (BRANCH 19.4A)	ICR

C 4170.07 (BRANCH 19.4A)	ICR
C 4170.09 (BEAVERFOOT - BR 34.7)	ICR
C 4170.10 (BEAVERFOOT - BR 32.9)	ICR
C 4170.12 (ICE BR 36.2)	ICR
C 4170.14 (WOLVERINE PASS)	ICR
C 4170.15 (ICE BR 33)	ICR
C 4170.19 [BRANCH 19.4B]	ICR
C 4170.21 [BRANCH 19.4D]	ICR
C 4170.22 [BRANCH 19.4D1]	ICR
C 4170.23 [MOOSE- BR 26.3]	ICR
C 4170.24 [MOOSE- BR 29.2]	ICR
C 4170.25 [MOOSE - Br 32.0]	ICR
C 4170.27 [WOLVERINE- BR 32.5]	ICR
C 5384.07 (BELL)	DCK
C 5384.08 (BELL - BR 10.1)	DCK
C 5384.09 (BELL - BR 8.1)	DCK
C 7521.06 [RED}	BWR
C 7521.18 (BUSH - BR 28)	BWR
C 7522.02 (REDROCK - YELLOW CR)	YLC
C 7522.04 (REDROCK - BR 11B)	RRH
C 7522.06 (REDROCK - BR 11D)	RRH
C 7522.13 (REDROCK - YELLOW CR BR 21.1A)	YLC
C 7522.15 (REDROCK - YELLOW CR BR 21.1 SPUR)	YLC
C 7604.02 (CUMMINS-BR 8.0)	X27
C 7663.05 (SMITH CR)	SWN
C 7663.08 (SWAN BR 66.8)	SWN
C 7667.03 (JUMPING CREEK - BR 3.6)	JCK
C 7764.01 [BIGMOUTH]	BGM
C 7764.02 (BIGMOUTH-LOUIS LEE)	BGM
C 7764.07 (BIGMOUTH - BR 25.2)	BGM
C 7764.08 (BIGMOUTH - BR 15.5)	BGM
C 7764.31 [BRANCH 500]	X55
C 8196.19 (FRISBY - BR 10.8)	FRR
C 8263.03 (NAGLE BR 4.0)	NGL
C 8263.04 (NAGLE BR 4.0A)	NGL
C 8263.05 (NAGLE BR 4.0B)	NGL
C 8263.06 (NAGLE BR 4.0B1)	NGL
C 8263.07 (NAGLE - BR6.3)	NGL
C 8637.02 (BEGBIE CR- BR 3)	X27
C 8637.03 (BEGBIE CR - BR 2)	X27
C 8962.01 (WETASK LAKE)	X27

C 9051.04 (MOUNT 7 - FOUR)	MTS
C 9051.07 (MOUNT 7 - SEVEN)	MTS
C 9051.10 (MOUNT 7 - TEN)	MTS
C 9354.02 (LIMEKILN)	T23
C 9354.07 (BRANCH 21.2)	T23
C 9354.08 (BRANCH 32.6)	T23
C 9354.09 (ODIN)	T23
C 9354.13 (BRANCH 22.0)	T23
C 9354.14 (BRANCH 19.9)	T23
C 9354.17 (BRANCH 21.0)	T23
C 9354.18 (BR 17.2)	T23
C 9354.19 (SHELTER BAY BR 21.9)	T23
C 9354.23 (BR 23.5)	T23
C 9357.02 (DAINARD CR - BR 1.0)	X07
C 9357.04 (DAINARD CR - BR 6.0)	X07
C 9617.03 (STITT CR - BR 37.1)	STN
C 9675.03 (BRANCH 3.1)	T23
C 9675.04 (BRANCH 3.6)	T23
C 9679.03 (KILLEEN BR 15.7)	RE
C 9679.08 (KILLEEN BR 18.2)	TFL23
C 9698.01 (GARRETT CREEK FSR)	GO
C 9698.02 (GARRETT CK BR 0.4)	GO
C 9698.03 (GARRETT CK BR 2.8)	GO
C 9698.04 (GARRETT CK BR 4.4)	GO
C 9698.06 (GARRETT CK NORTH FSR)	GO
C 9698.07 (GARRETT CK N BR 1.4)	GO
C 9698.10 (GARRETT CK N BR 3.2)	GO
C 9981.10 (SHAKETOWN)	T23
C 9981.17 (RIVERSIDE)	T23
C 9981.18 (RIVERSIDE BR A)	T23
CN 0724.09 (CELISTA BR. 1)	CLS
CN 0724.10 (CELISTA BR. 2)	CLS
CN 7271.07 (BLAIS SOUTH)	BLS
N 0652.06 (K3BL.01)	KWK
N 0771.10 (SCOTCH-PASS)	LMB
N 0771.14 (SCOTCH-HLINA WEST)	HLN
N 0771.15 (SCOTCH-STUB BR. 1)	LMB
N 0771.27 (K5D6.01)	HLN
N 0825.07 (HAINES CR - WALL CR N.)	WCK
N 0825.08 (HAINES CR - WALL CR E.)	WCK
N 0825.09 (MOUNT IDA - HOBSON)	MTI

N 0905.19 (SUGAR - REIBEL)	IRE
N 10186.05 (LITTLE WHITE LAKE - LEOWSKI BR 6.8)	WLK
N 1030.05 (REDWOOD)	IRE
N 1030.06 (CAMDEN)	IRE
N 1030.07 (CARBINE)	IRE
N 1030.13 (OATLEY)	IRE
N 1030.14 (OATLEY - 100)	IRE
N 1030.16 (DUFFY)	IRE
N 1030.20 (COLLEEN CREEK)	IRE
N 1030.22 (DEAN)	IRE
N 1030.23 (DRAYDEN)	IRE
N 1030.24 (SCHMIDT)	IRE
N 1030.25 (MADI MAIN)	IRE
N 1030.26 (SOCHI)	IRE
N 1030.28 (COLT)	IRE
N 1031.23 (DUSTIN)	HAR
N 1031.44 (COPLEY)	HAR
N 1031.53 (K5SG.01)	HAR
N 1031.54 (K710.01)	HAR
N 1031.55 (K70X.01)	HAR
N 1031.56 (K710.04)	HAR
N 1031.57 (K72G.03)	HAR
N 1031.58 (H300EXT)	HAR
N 1031.62 (AK1PB)	HAR
N 1031.63 (AK1PC)	HAR
N 1031.64 (AK1PD)	HAR
N 1031.65 (AK1PE)	HAR
N 1031.66 (AK1PF)	HAR
N 1031.72 (K70V.01)	HAR
N 1109.08 (SUMMER)	ECH
N 1109.15 (CLOUDY)	ECH
N 1109.17 (SWELL)	ECH
N 1109.18 (K26V.01)	ECH
N 4123.08 (FLY HILLS - BRANCHFLOWER)	BFL
N 4123.09 (- BRANCHFLOWER SPUR 1)	BFL
N 4123.10 (- BRANCHFLOWER SPUR 2)	BFL
N 4123.11 (- BRANCHFLOWER SPUR 3)	BFL
N 4848.20 (LUMBER)	MSC
N 4848.21 (K6E4.00)	MSC
N 4848.22 (K6E4.01)	MSC
N 4848.23 (K6E4.06)	MSC

N 5143.15 (ASHTON -RESEARCH CONNECTOR)	MSC
N 5143.21 (K6VE.01)	HBL
N 5653.35 (EVERY)	WLK
N 6019.04 (CHARCOAL- SKIMIKIN)	SKM
N 6019.11 (K6FL.01)	SKM
N 7452.03 (SICAMOUS CR. BRANCH 2)	MSC
N 7452.04 (SICAMOUS CR. NORTH)	MSC
N 7657.50 (K292.02)	CST
N 7657.51 (K292.01)	CST
N 7657.52 (K5BM.01.03)	CST
N 8215.11 (CONNER)	CRR
N 8255.04 (K6R2.00)	MSC
N 8332.09 (CHASE CR.-BR. 2)	CHR
N 8435.36 (LV2163.02)	KTL
N 8969.03 (CHUM LAKE-BR. 3)	CHM
N 8969.06 (CHUM LAKE-BR. 6)	CHM
N 8969.09 (SAVANNA)	CHM
N 8969.10 (HAREWOOD)	CHM
N 8969.11 (K6XZ.01)	CHM
N 9659.04 (FITZROY)	CHR
S 10053.02 (ONCOR)	WHD
S 10181.06 (K6QB.01)	BAN
S 10649.10 [CHILLA]	MSN
S 10924.06 [K6QM 01]	BAN
S 4123.14 [K6WB]	BLN
S 7654.120 (K6F9-01)	GRS
S 7654.159 [K5UZ]	GRS
S 7654.34 [BUSTER SPUR1]	GRS
S 7654.35 [BUSTER SPUR2]	GRS
S 7654.36 [BUSTER SPUR3]	GRS
S 7654.37 [BUSTER SPUR4]	GRS
S 7654.43 [BAUMEN WEST]	GRS
S 7654.46 [KEATON]	GRS
S 7654.47 [VILLA]	GRS
S 7654.48 [COOK]	GRS
S 7654.57 (BEBLOW - 300)	SKH
S 7654.58 (BEBLOW - 400)	SKH
S 7654.82 (K59B)	SKH
S 7654.87 (K6EU-1)	SKH
S 7654.90 (K6FU-A)	SKH
S 7654.92 (K6EP-A)	SKH

S 7654.93 (K6EP-B)	SKH
S 7654.97 (K6JH)	GRS
S 7654.98 (K6JJ)	GRS
S 7666.11 (MOWING MACHINE 4230)	BRT
S 7666.16 (MOWING MACHINE 4230-3)	BRT
S 7666.17 (MOWING MACHINE 4380)	BRT
S 7666.21 (SALMON RIVER - 4060)	BRT
S 7720.22 (ESPERON 200)	STT
S 7720.23 (SMALLEY)	STT
S 8399.03 (WEST)	PXT
S 8399.11 (K7GM.01)	PXT
S 8435.38 [RANGER CREEK]	BAN
S 8435.40 [FRED]	BAN
S 8569.07 (NORTH)	BRT
S 8569.56 (K5YX)	BRT
S 8569.63 (K67R-A)	BRT
S 8569.66 (K7KX.01)	BRT
S 8692.15 (K6P0-01)	MSN
S 8692.16 (K6P0-03)	MSN
S 8692.37 [K6NL]	MSN
S 8693.15 [KETTLE LINK]	GRS
S 8693.16 [THORN]	GRS
S 8693.33 (K697-A)	GRS
S 8693.34 (K697-B)	GRS
S 8693.35 (K697-C)	GRS
S 8693.36 (K697-D)	GRS
S 8694.04 (BIG FIR)	GLK
S 8701.06 (K6BW.01)	SKH
S 8717.04 (K6PF)	SKH
S 8717.05 (K6SP-M2)	SKH
S 8717.06 (K6SP-07A)	SKH
S 8717.07 (K6SP-05A)	SKH
S 9179.10 (K6BC)	SKH
S 9555.01 (BOULDER)	MWY
S 9578.01 (OLD DAVE)	ODV