Spruce Bark Beetle Report 2015 Fall

2015-PAR-027

ADMINISTRATION

Polygon: PAR027 **Hectares**: 86.15 **Exact Location**: near 62km on the Parsnip West FSR

Walkthrough: 4700 **Number of Probe Pixels**: 2 **Date**: 2015.10.13 **Crew**: D. Norwell, M. Vanderstap

STAND INFORMATION

Site Description: (topography, terrain, timber types, stand age, influences)

This stand straddles the lower Scott Creek drainage, steep banked sides but flattish around the creek itself. Beaver activity is abundant in the polygon, as well as blowdown, both exacerbating the maneuverability getting around this stand. Blowdown is old and new, some with attack. Due to its lengthy nature this unit has various boundaries throughout its length, cutblocks, roads and mature and immature timber. There is also rock faces and rocky outcrops in various locations. The stand is comprised mainly of mature susceptible spruce in the lower sections with balsam fir leading in the upper sections, likely due to elevation.

Stand Susceptibility: Moderate **Access**: 4WD, ATV

Other Considerations or Limiting Factors: major drainage, poor access, riparian areas, beaver activity

SUMMARY OF CURRENT INFESTATION:

Attack can be heavy at times, and generally located near the creek on the flatter portions of the polygon. Current attack on a two year cycle, along with abundant code fives.

Volume Healthy	*Volume Year One Attack*	*Volume Year Two Attack*		*Volume Old Attack*	
343.6	97.5	0		70.6	
Bark Sample Data	***Entrance Holes***	***Adults***	***Larvae***	***Pupae***	***Young Adults***
(combined)	16	7	38	1	1

BRITISH COLUMBIA BEETLE PROBE CARD

LOCATION	ELEVATION	LATITUDE	PAGE	OF
04-7006 7/6183171	833m			

BEARING	STRIP LINE NO	STRIP WIDTH	DISTANCE	BEETLE SPECIES
210°	ONE2-1	10m	100m	[X] SB [ ] MPB [ ] DFB

DIAMETER CLASS	SURFACE AREA FACTOR	NUMBER OF HEALTHY HOSTS	BARK BEETLE CODE BY YEAR OF ATTACK 1	2	3	4	5	6	OTHER TREE SPECIES MAIN	OTHER
									BL	
12.5 - 17.4	2.0									
17.5 - 25.0	3.3									
25.1 - 30.0	5.3									
30.1 - 35.0	7.1									
35.1 - 40.0	9.4									
40.1 - 45.0	11.6									
45.1 - 50.0	13.8									
50.1 - 55.0	16.2									
55.1 - 60.0	18.7									
60.1 -	25.3									
TOTALS										

BARK SAMPLES 15cm x 15cm	NO ENTRANCE HOLES	NO PARENT ADULTS	NO LARVAE	NO PUPAE	NO CALLOW ADULTS	FRESH (GREEN) BLOWDOWN Attacked	Unattacked
N	5	3	12	✓	✓		
S	4	4	10	1	1		

COMMENTS
090
B.S.A.P.
PARALLELS CREEK 1ST [illegible] was PO at bottom [illegible] FLAT

CREW NAMES	DATE Y	M	D
DAVID NORDELL	2015	10	14

FS 1111A RPG 00/02 7530881049 (100/bdl)

BRITISH COLUMBIA BEETLE PROBE CARD

LOCATION	ELEVATION	LATITUDE	PAGE	OF
55°46.614'N 123°30.652'	266 Ft			

BEARING	STRIP LINE NO	STRIP WIDTH	DISTANCE	BEETLE SPECIES
45°		10m	100m	[X] SB [ ] MPB [ ] DFB

DIAMETER CLASS	SURFACE AREA FACTOR	NUMBER OF HEALTHY HOSTS	BARK BEETLE CODE BY YEAR OF ATTACK 1	2	3	4	5	6	OTHER TREE SPECIES MAIN	OTHER
									D	
12.5 - 17.4	2.0									
17.5 - 25.0	3.3									
25.1 - 30.0	5.3									
30.1 - 35.0	7.1									
35.1 - 40.0	9.4									
40.1 - 45.0	11.6									
45.1 - 50.0	13.8									
50.1 - 55.0	16.2									
55.1 - 60.0	18.7									
60.1 -	25.3									
TOTALS										

BARK SAMPLES 15cm x 15cm	NO ENTRANCE HOLES	NO PARENT ADULTS	NO LARVAE	NO PUPAE	NO CALLOW ADULTS	FRESH (GREEN) BLOWDOWN Attacked	Unattacked
N	4	0	16	0	0		
S	3	0	0	1	1		

COMMENTS Stead only pupae / callow. Unsure what it was. S. side more stain + very deep Think code 4 and 1 N side all brood chewed entrances most pitched out.

CREW NAMES	DATE Y	M	D
MS			

FS 1111A RPG 00/02 7530881049 (100/bdl)



STRIP NO.: 1 DIRECTION: 215°

START STRIP: 408440 - 6181896

JOB NO.: FH16mk006 DATE: Oct 13 2015

CREW: Mariska van der Stap

REMARKS:

www.irlsupplies.com
Ph: 1-800-663-6843



STRIP NO.: 3 DIRECTION: 45°

START STRIP: 467665 - 6181087

JOB NO.: FH16mk006 DATE: Oct 13 2015

CREW: Mariska van der Stap

REMARKS:

www.irlsupplies.com
Ph: 1-800-663-6843

TOPOGRAPHY STRIP No. MS1 +2 TIMBER TYPE


POT SL2
145
100
50
50%
level
SL2 POC
1040 SL1 Pot.
1000
40%
Class 6
70%
900
800
40%
Class 6
700
200m
S-L
200m
200m
S-L
200m
slope so chang
SB
SB
SB



STRIP NO.: DN01 DIRECTION: 40° (Looped down to follow Game trail by high Sus. Creek)

START STRIP: 0469671/6182693

JOB NO.: FOR 2K DATE: OCT 13 2015

CREW: DAVID NORWELL

REMARKS:

www.irlsupplies.com
Ph: 1-800-663-6843



STRIP NO.: DN03 DIRECTION: 76° AT 300m

START STRIP: END DN02

JOB NO.: PAR 2K DATE: OCT 13 2015

CREW: DAVID NORWELL

REMARKS:

www.irlsupplies.com
Ph: 1-800-663-6843



STRIP NO.: DN05 DIRECTION: 250°

START STRIP: 0469634/6182583

JOB NO.: PAR 27 DATE: Oct 13

CREW: DAVID NORWELL

REMARKS: CREEK TRAVERSE AT STRT
FOLLOW TRACK, LOTS OF B.D

www.irlsupplies.com
Ph: 1-800-663-6843