SENECA ENTERPRISES LTD.
PO BOX 1902, PRINCE GEORGE, BC, V2L 5E3
Phone: (250) 561-0890, Fax: (250) 564-3275

SPRUCE BARK BEETLE REPORT
FH17DPG218

STAR PROBE# **2016-BLA-0175** 60

NUMBER OF CODE 1-4 ATTACK 0

PROBE LINE NO

SUMMARY OF CURRENT INFESTATION

NO ATTACK

Star Probe had no attack, site so wet and flooded couldn't reach plot centre, north and east.



ACCESS

From ATV , walk 400m at 60 degrees

SITE FEATURES (Topography, Terrain, Timber Types, Age)

Very wet ground, Moderate slope 0-10%, 60% Balsam, 40% spruce

SIZE, BOUNDARY and PATTERN OF INFESTATION

No current attack

INCIDENCE AND SEVERITY OF ATTACK

No current attack.

RISK OF BEETLE SPREAD and SURROUNDING SITES

No current attack found minimal signs in area

ACCESS, OPERABILITY and INTEGRATED RESOURCE MGMT ISSUES

Very Wet site, walked 400 m to site

RECOMMENDATIONS

OPTION 1 **NO ACTION**

OPTION 2

Site 60



*due to warm weather & rainfall, entire NW, SW flooded can not reach centre.

Cecilia French + Khady Bogdan

R.D. PENHALL LTD. MADE IN VANCOUVER, CANADA
DUKSBAK WATERPROOF

FIELD