SENECA ENTERPRISES LTD.
PO BOX 1902, PRINCE GEORGE, BC, V2L 5E3
Phone: (250) 561-0890, Fax: (250) 564-3275

SPRUCE BARK BEETLE REPORT
FH17DPG218

STAR PROBE# **2016-CLE-0064** 514

NUMBER OF CODE 1-4 ATTACK 0

PROBE LINE NO

SUMMARY OF CURRENT INFESTATION

NO ATTACK

Star Probe had no signs of attack. Overlaps with site 2016-CLE-0064 and main road.



ACCESS

Right off Clearwater FSR, has Clearwater river run through it, steep, found a crossing to other side of it,.

SITE FEATURES (Topography, Terrain, Timber Types, Age)

River divides site, Steep dropoff into site.

SIZE, BOUNDARY and PATTERN OF INFESTATION

No attack.

INCIDENCE AND SEVERITY OF ATTACK

No attack.

RISK OF BEETLE SPREAD and SURROUNDING SITES

No attack.

ACCESS, OPERABILITY and INTEGRATED RESOURCE MANAGEMENT ISSUES

Adjacent to road. River runs through it.

RECOMMENDATIONS

OPTION 1 **TRAP TREE TRAILS**

As access good, establish trap tree trail alongside road within site to get beetles from adjacent site 2016-CLE-0065.

OPTION 2 **MONITOR/ EST. POLYGON**

Monitor and/or create a polygon along east side of river to incorporate attack in area and better measure impact of attack.,



514



Access - walked from truck @ 10U0502802 6166944

514 Plot Centre - 10U0502802 6166908

Aaron Colebank Nov 6th, 2016

⊛ No live attack

R.D. PENHALL LTD., MADE IN VANCOUVER, CANADA
DUKSBAK WATERPROOF

METRIC FIELD