SENECA ENTERPRISES LTD.
PO BOX 1902, PRINCE GEORGE, BC, V2L 5E3
Phone: (250) 561-0890, Fax: (250) 564-3275

SPRUCE BARK BEETLE REPORT
FH17DPG218

STAR PROBE# **2016-KEN-0004** 312

NUMBER OF CODE 1-4 ATTACK 0

PROBE LINE NO

SUMMARY OF CURRENT INFESTATION

NO ATTACK

Star probe had no signs of attack. Located in a draw with river.

ACCESS

From truck in cutblock, walk 800m west to site

SITE FEATURES (Topography, Terrain, Timber Types, Age)

Relatively flat, river runs through it

SIZE, BOUNDARY and PATTERN OF INFESTATION

No Attack in or around site, surrounded by cutblocks

INCIDENCE AND SEVERITY OF ATTACK

No Current Attack

RISK OF BEETLE SPREAD and SURROUNDING SITES

No current attack, surrounded by cutblocks.

ACCESS, OPERABILITY and INTEGRATED RESOURCE MGMT ISSUES

Site surrounded by cutblocks, in a draw.

RECOMMENDATIONS

OPTION 1 **NO ACTION**

No Current Attack, no action required.

OPTION 2





R.D. PENHALL LTD. MADE IN VANCOUVER, CANADA
DUKSBAK WATERPROOF

METRIC FIELD