SENECA ENTERPRISES LTD.
PO BOX 1902, PRINCE GEORGE, BC, V2L 5E3
Phone: (250) 561-0890, Fax: (250) 564-3275

SPRUCE BARK BEETLE REPORT
FH17DPG218

STAR PROBE# **2016-MIS-0057** 318

NUMBER OF CODE 1-4 ATTACK 0

PROBE LINE NO

SUMMARY OF CURRENT INFESTATION

NO CURRENT ATTACK

Site isolated with 3 code 5 older attack trees found. Newer plantation on edge of site/

ACCESS

From truck ewalk through plantation 435m @118degrees

SITE FEATURES (Topography, Terrain, Timber Types, Age)

Blowdown runs along cutblock. Some Large Spruce and Balsam, low volume density

SIZE, BOUNDARY and PATTERN OF INFESTATION

No Current attack found, evidence of old attack, no other sites in immediate area

INCIDENCE AND SEVERITY OF ATTACK

No Current Attack Found

RISK OF BEETLE SPREAD and SURROUNDING SITES

No Current Attack in site or area, boundaried by cutblock



ACCESS, OPERABILITY and INTEGRATED RESOURCE MGMT ISSUES

Walked in 400 m, edge of plantation, blowdown.

RECOMMENDATIONS

OPTION 1 **NO ACTION**

No current attack found.

318 [illegible]

Nov 5th

JK, DD



Attack - C5:3

Access - From truck, walk 435m @ 118°.
Most is walking through plantation.

Features - Blowdown runs along cutblock.
Some large Sx ? Bl. low
Volume density.



318 0513925
6098260

No. V 5
DD/JJ

FLAT GROUND
AVG DIA 40-45
70% SPRUCE 30% BALSAM

R.D. PENHALL LTD. MADE IN VANCOUVER, CANADA
DUKSBAK WATERPROOF
METRIC FIELD