SENECA ENTERPRISES LTD.
PO BOX 1902, PRINCE GEORGE, BC, V2L 5E3
Phone: (250) 561-0890, Fax: (250) 564-3275

SPRUCE BARK BEETLE REPORT
FH17DPG218

STAR PROBE# **2016-PHI-0071** 150

NUMBER OF CODE 1-4 ATTACK 0

PROBE LINE NO

SUMMARY OF CURRENT INFESTATION **NO ATTACK**

Grouping of sites PHI0067, 0068, 0069, 0070 and 0071. These sites all surround cutblocks and have no signs of attack other than 0070 which had 1-Code 5 Older attack.

ACCESS

From truck all sites walkin through cutblocks 100-500 m.

SITE FEATURES (Topography, Terrain, Timber Types, Age)

Mostly strips between cutblocks, all on edges of cutblocks with sparse stands with heavy alder.

SIZE, BOUNDARY and PATTERN OF INFESTATION

No current attack noticed

INCIDENCE AND SEVERITY OF ATTACK

No current attack noticed

RISK OF BEETLE SPREAD and SURROUNDING SITES

Minimal. All sites had no current attack and are boundaried by cutblocks which will limit any beetle spread.

ACCESS, OPERABILITY and INTEGRATED RESOURCE MGMT ISSUES

All good access through existing cutblocks.

RECOMMENDATIONS

OPTION 1 **NO ACTION**

No Recent attack noticed.





150



NW 3RD

MA, MV

Attack - No signs

Access - 150m @ 190° from truck

features - heavy alder within site and minimal SX & BI

156