SENECA ENTERPRISES LTD.
PO BOX 1902, PRINCE GEORGE, BC, V2L 5E3
Phone: (250) 561-0890, Fax: (250) 564-3275

SPRUCE BARK BEETLE REPORT FH17DPG218

STAR PROBE# **2016-PHI-0125** 206

NUMBER OF CODE 1-4 ATTACK 0

PROBE LINE NO

SUMMARY OF CURRENT INFESTATION

NO ATTACK

Grouping of sites PHI-0123, 0124, 0125 and 0126. All sites are west of mainline and all surrounded by fresh cutblocks. Very light attack with sites PHI-0123 and PHI-0124 Having Isolated single Code 3 Attack with light Sanitation priority ratings. Other sites no signs of attack.

ACCESS

From truck, walk 600m to 2.2km west to sites

SITE FEATURES (Topography, Terrain, Timber Types, Age)

Site 0123 has Stream along North, cutblock to west. Site 0124 open stand with cutblock at 30m East. Site 0125 has cutblock at 50m to the north. Site 0126 has Heavy Balsam in stand.

SIZE, BOUNDARY and PATTERN OF INFESTATION

Surrounded by cutblocks with 2 sites having single Code 3 attacked trees. Very isolated light scattered attack.

INCIDENCE AND SEVERITY OF ATTACK

Surrounded by cutblocks with 2 sites having single Code 3 attacked trees. Very isolated light scattered attack amongst sparse spruce stands with smaller DBH



RISK OF BEETLE SPREAD and SURROUNDING SITES

Minimal. Sites 0123 and 0124 has one current attacked tree amongst low volume of spruce. All sites are surrounded by fresher cutblocks.

ACCESS, OPERABILITY and INTEGRATED RESOURCE MGMT ISSUES

All accessed Wets of mainline, from a 600m walk in to 2.4km. All boundary new fresh cutblocks and is just some spillover trees with minimal impact expected.

RECOMMENDATIONS

OPTION 1 **NO ACTION**

Although beetle will fly in 2017 in 0123 and 0124, very light single Code 3 attacked trees, Areas surrounded by fresh logging.



SITE 206

- Oct 27, 2016
- AC
- NO CURRENT ATTACK
- Cutblock 50m North West mainly alder
- 60% Sx 40% BL
- Avg DBH 25-30



206



206 Access = walked from truck @ 10U 0490922 6109374

206 Plot Centre = 10U 0489277 6109126

Aaron Colebank Oct 27th, 2016

(N) Cut block @ 50m North west line is mostly alder :-
No live attack found.

R.D. PENHALL LTD. MADE IN VANCOUVER, CANADA
DUKSBAK WATERPROOF

METRIC FIELD

BRITISH COLUMBIA — BEETLE PROBE CARD

LOCATION	ELEVATION	LATITUDE	PAGE	OF
206 East line	825	10 U 0489277 6109126		

BEARING	STRIP LINE NO	STRIP WIDTH	DISTANCE	BEETLE SPECIES
90°	East	10 m	100m	[X] SB [ ] MPB [ ] DFB

DIAMETER CLASS	SURFACE AREA FACTOR	NUMBER OF HEALTHY HOSTS	BARK BEETLE CODE BY YEAR OF ATTACK 1	2	3	4	5	6	OTHER TREE SPECIES MAIN	OTHER
									B1	
12.5 - 17.4	2.0									
17.5 - 25.0	3.3	•							• • •	
25.1 - 30.0	5.3								• •	
30.1 - 35.0	7.1	•							•	
35.1 - 40.0	9.4	— • •								
40.1 - 45.0	11.6	• • •							• •	
45.1 - 50.0	13.8									
50.1 - 55.0	16.2									
55.1 - 60.0	18.7									
60.1 -	25.3	•								
TOTALS		11							8	

BARK SAMPLES 15cm x 15cm	NO. ENTRANCE HOLES	NO. PARENT ADULTS	NO. LARVAE	NO. PUPAE	NO. CALLOW ADULTS	FRESH (GREEN) BLOWDOWN Attacked		Unattacked

COMMENTS: No live attack found

CREW NAMES: Aaron Colebank

DATE: Y 2016 M 10 D 27

FS 1111A RPG 00/02 7530881049 (100/bdl)