FH17DPG218- SUMMARY - PINE PASS NORTH

93O10	594	2016-PINN-0011	0.25	Pine Pass North	10	CODE 1-4	0	CODE 5-6	MODERATE ATTACK	TRAP TREES	FALL AND BURN
93O10	595	2016-PINN-0012	0.25	Pine Pass North	3	CODE 1-4	0	CODE 5-6	MODERATE ATTACK	TRAP TREES	FALL AND BURN
93O10	605	2016-PINN-0021	0.25	Pine Pass North	2	CODE 1-4	1	CODE 5-6	LIGHT ATTACK	NO ACTION	
93O10	606	2016-PINN-0022	0.25	Pine Pass North	0	CODE 1-4	2	CODE 5-6	NO CURRENT ATTACK	NO ACTION	
93O10	607	2016-PINN-0023	0.25	Pine Pass North	0	CODE 1-4	0	CODE 5-6	NO CURRENT ATTACK	NO ACTION	
93O10	624	2016-PINN-0029	0.25	Pine Pass North	0	CODE 1-4	5	CODE 5-6	NO CURRENT ATTACK	NO ACTION	
93O10	584	2016-PINN-0001	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	585	2016-PINN-0002	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	586	2016-PINN-0003	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	587	2016-PINN-0004	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	588	2016-PINN-0005	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	589	2016-PINN-0006	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	590	2016-PINN-0007	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	591	2016-PINN-0008	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	592	2016-PINN-0009	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	593	2016-PINN-0010	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	596	2016-PINN-0013	0.25	Pine Pass North		River					
93O10	597	2016-PINN-0014	0.25	Pine Pass North	NO ACCESS	River					
93O10	598	2016-PINN-0015	0.25	Pine Pass North	NO ACCESS	River					
93O10	599	2016-PINN-0016	0.25	Pine Pass North	NO ACCESS	River					
93O10	600	2016-PINN-0017	0.25	Pine Pass North	NO ACCESS	River					
93O10	601	2016-PINN-0018	0.25	Pine Pass North	NO ACCESS	Greater Than 1.5km					
93O10	602	2016-PINN-0019	0.25	Pine Pass North	NO ACCESS	River					
93O10	603	2016-PINN-0020	0.25	Pine Pass North	NO ACCESS	River					
93O10	608	2016-PINN-0024	0.25	Pine Pass North		Too Steep					
93O10	618	2016-PINN-0025	0.25	Pine Pass North	NO ACCESS	Bridge Out					
93O10	619	2016-PINN-0026	0.25	Pine Pass North		Bridge Out					
93O10	621	2016-PINN-0027	0.25	Pine Pass North		Bridge Out					
93O10	623	2016-PINN-0028	0.25	Pine Pass North		Bridge Out					

Area Pine Pass north has two sites where treatment is recommended. They are isolated sites up a steep slope and have moderate attack and with beetle moving further out, will become inaccessible. To slow movement, Trap Trees with burning or Fall and Burn treatment could be implemented. Other sites light scattered attack or no current attack and no treatment required.

Lots of sites inaccessible as bridge pulled crossing the clearwater river. Some other are blocked by river or logistically too far away from mainline or ATV access and operationally too steep.