Access: Access Via a Pipeline, upgrade and permission would be required to access for treatments



Operability – Flat to 50% slope - operable

Resource Management Concerns – Oil and Gas operations in the area. Be aware of permissions and H2S related concerns

Vigour of Beetle population – Some mountain pine beetle kill was noted in addition to spruce beetle kill.
Spruce is the secondary species in this stand.

Other Factors – N/A

Dawson Creek Sx Beetle Probe

Block 1804 Final Map

Legend

- Block of Interest
- Dead Attack
- Live Attack
- No Attack
- Surrounding Blocks
- Pixels
- Tracks
- Roads
- Roads - Condition Unknown
- Contours_50k
- Lakes/Rivers
- Streams

FH198240003

Date Surveyed: Dec 12, 2018
Surveyors: Jorian Todd
Area Surveyed: 13.6 Ha
Total Walkthrough Distance: 1.36 km
Percent of Walk Line Distance [100m segments] with Live Beetles: 7.3 %
Number Pixels Surveyed: 1
Pixel Data - Attack Percentages by Yr. of Attack:

- (2018) 0.0 %
- (2017) 0.0 %
- (2016) 0.0 %

Pixel Data - Percent Spruce: 54.3 %
Sanitation and Salvage Harvest Rate: 0.0
Monitor through aerial program

Mapping Date: 2/15/2019

Mapper: Niki Rosenthal

Data Source: BCGW

N W E S

Scale: 1:10,000

0 120 240 360 480 600
Meters

This map is georeferenced
Coordinate System: NAD 1983 BC Environment Albers