Access: Drive to lease site on South Bullmoose Road. Sled part way along block road. Depending on snow levels at deactivation walk to the polygon. If snow levels are acceptable walk 400 m to polygon



Operability – 40 – 60 % slope generally. Should be operable.

Resource Management Concerns – Two creeks that were not classified due to snow levels

Vigour of Beetle population – No live attack to determine vigour. But 6 dead trees were noted, so it has been present.

Other Factors – N/A

Dawson Creek
Sx Beetle Probe

Block 452
Final Map

Legend

- Block of Interest
- Dead Attack
- Live Attack
- No Attack
- Surrounding Blocks
- Pixels
- Tracks
- Roads
- Roads - Condition Unknown
- Contours_50k
- Lakes/Rivers
- Streams

FH198240003

Date Surveyed: December 18, 2018
Surveyors: Jorian Todd
Area Surveyed: 19Ha
Total Walkthrough Distance: 1.90 km
Percent of Walk Line Distance [100m segments] with Live Beetles: 0.0 %
Number Pixels Surveyed: 1
Pixel Data - Attack Percentages by Yr. of Attack:

- [2018] 0.0 %
- [2017] 0.0 %
- [2016] 0.0 %

Pixel Data - Percent Spruce: 78.93 %
Sanitation and Salvage Harvest Rate: 0.00
Monitor through aerial program

Mapping Date: 2/15/2019

Mapper: Niki Rosenthal

Data Source: BCGW

N W E S

Scale: 1:10,000

0 120 240 360 480 600
Meters

This map is georeferenced
Coordinate System: NAD 1983 BC Environment Albers