Access: Adjacent to Hwy 97.



Dawson Creek Sx Beetle Probe

Block 51724 Final Map

Legend

- Block of Interest
- Dead Attack
- Live Attack
- No Attack
- Surrounding Blocks
- Pixels
- Tracks
- Roads
- Roads - Condition Unknown
- Contours_50k
- Lakes/Rivers
- Streams

FH198240003

Date Surveyed: December 5-6, 13, 2018
Surveyors: Matt Crowe, Danielle fisher, Connor Toop, Marcus Vander Meulen, Jorian Todd
Area Surveyed: 34.4 Ha
Total Walkthrough Distance: 3.45 km
Percent of Walk Line Distance [100m segments] with Live Beetles: 72 %
Number Pixels Surveyed: 2
Pixel Data - Attack Percentages by Yr. of Attack:

- (2018) 0.00 %
- (2017) 12.71 %
- (2016) 0.00 %

Pixel Data - Percent Spruce: 77.99 %
Sanitation and Salvage Harvest Rate: 660.63
Moderate – Selective log and haul dead and attacked trees in areas outside Riparian Management Area, Prior to May 2019. Trap trees within Riparian Management Area winter 2018/2019, burn fall of 2019.

Comments: Trees 30m + away from center line on walkthrough were assessed in this polygon (60% coverage). Adjacent to the Pine River which is eroding polygon. Riparian management. Wetlands outside and

Mapping Date: 1/22/2019

Mapper: Niki Rosenthal

Data Source: BCGW

N
W E
S

Scale: 1:10,000

0 120 240 360 480 600
Meters

This map is georeferenced
Coordinate System: NAD 1983 BC Environment Albers