Access: Very Back of the Moberly FSR. Main-line has been deactivated and washed out. Secondary road was sledable to a point. Spur road washed out. Walk 500 m crossing frozen river, or 1 km from closest road. Choose walking route carefully due to steep slopes and cliffs



Operability – Steep slopes closest to river. Southern edge of the polygon is likely operable.

Resource Management Concerns – River runs along northern edge. Majority of the block is likely in a Riparian Zone.

Vigour of Beetle population – No live attack noted. A few dead attack.

Other Factors – N/A

SPECTRUM RESOURCE GROUP INC

Dawson Creek Sx Beetle Probe

Block 52305 Final Map

Legend

- Block of Interest
- Dead Attack
- Live Attack
- No Attack
- Surrounding Blocks
- Pixels
- Tracks
- Roads
- Roads - Condition Unknown
- Contours_50k
- Lakes/Rivers
- Streams

Mapping Date: 2/15/2019

Mapper: Niki Rosenthal

Data Source: BCGW

N W E S

Scale: 1:10,000

0 120 240 360 480 600

Meters

This map is georeferenced
Coordinate System: NAD 1983 BC Environment Albers