Access: Very back of the Moberly. Deactivated and washout out mainline. 600 m walk up hill from the closest sledable, access road.



Operability – Slopes 60-100 %

Resource Management Concerns – Riparian zone. Creek classification not confirmed due to snow levels.

Vigour of Beetle population – Scatted live beetle around streams. Scattered code 5 throughout polygon. Significant component of Sub-Alpine fir throughout the polygon. Less than 50 % of the stand is Spruce.

Other Factors – N/A

SPECTRUM RESOURCE GROUP INC

Dawson Creek Sx Beetle Probe

Block 57535 Final Map

Legend

- Block of Interest
- Dead Attack
- Live Attack
- No Attack
- Surrounding Blocks
- Pixels
- Tracks
- Roads
- Roads - Condition Unknown
- Contours_50k
- Lakes/Rivers
- Streams

FH198240003

Date Surveyed: January 26, 2019
Surveyors: Simon Turcotte
Area Surveyed: 13.4 Ha
Total Walkthrough Distance: 1.4 km
Percent of Walk Line Distance [100m segments] with Live Beetles: 35 %
Number Pixels Surveyed: 1
Pixel Data - Attack Percentages by Yr. of Attack:

- (2018) 0.00 %
- (2017) 0.00 %
- (2016) 0.00 %

Pixel Data - Percent Spruce: 45.25 %
Sanitation and Salvage Harvest Rate: 0.00
Leave as is

Mapping Date: 2/15/2019

Mapper: Niki Rosenthal

Data Source: BCGW

N W E S

Scale: 1:10,000

0 120 240 360 480 600
Meters

This map is georeferenced
Coordinate System: NAD 1983 BC Environment Albers