Access: Very Back of the Moberly FSR. Mainline has been deactivated and washed out. Secondary road was sledable.



Operability – 40-50 % slope consistent throughout the polygon. Cliffs were noted throughout

Resource Management Concerns – Multiple streams throughout. Classification could not be completed at time of assessment. Cariboo?

Vigour of Beetle population – 2-year life cycle on all trees. Spruce is the leading species in the overstory with Sub-alpine fir as the secondary species. Majority of spruce are still on the smaller diameter size.

Other Factors – N/A

Dawson Creek Sx Beetle Probe

Block 57548 Final Map

Legend

- Block of Interest
- Dead Attack
- Live Attack
- No Attack
- Surrounding Blocks
- Pixels
- Tracks
- Roads
- Roads - Condition Unknown
- Contours_50k
- Lakes/Rivers
- Streams

FH198240003

Date Surveyed: January 28-30, 2019
Surveyors: Connor Topp, Aiden Wischnewski
Area Surveyed: 67.5 Ha
Total Walkthrough Distance: 6.77 km
Percent of Walk Line Distance [100m segments] with Live Beetles: 60.5 %
Number Pixels Surveyed: 2
Pixel Data - Attack Percentages by Yr. of Attack:

- (2018) 0.00 %
- (2017) 2.56 %
- (2016) 7.22 %

Pixel Data - Percent Spruce: 64.07 %
Sanitation and Salvage Harvest Rate: 225.10
Trap trees – winter of 2018/2019
Burn and remove winter of 2019/2020

Mapping Date: 2/08/2019

Mapper: Niki Rosenthal

Data Source: BCGW

N W E S

Scale: 1:10,000

0 120 240 360 480 600
Meters

This map is georeferenced
Coordinate System: NAD 1983 BC Environment Albers