Access: Polygon is access through a new cut block. Walk 300 m to the West edge of the block for the east side of the polygon. West side of Canyon is access from a different road.



Operability – The central portion of the polygon is not operable or safe for ground crew. This area was not surveyed. Western and eastern edges, overall should be operable, with some areas not due to slope

Resource Management Concerns – Creeks/gullies that lead to a significant waterway. Riparian Management Zone. Terrain stability/Erosion concerns in central portion of the polygon.

Vigour of Beetle population – Mixedwood stand with small scattered patches of live and dead attack. Low vigour

Other Factors – N/A

SPECTRUM RESOURCE GROUP INC

Dawson Creek
Sx Beetle Probe

Block 66484
Final Map

Legend

- Block of Interest
- Dead Attack
- Live Attack
- No Attack
- Surrounding Blocks
- Pixels
- Tracks
- Roads
- Roads - Condition Unknown
- Contours_50k
- Lakes/Rivers
- Streams

FH198240003

Date Surveyed: January 25, 30, 2019
Surveyors: Mariska Van Der Stap, Simon Turcotte
Area Surveyed: 52.4 Ha
Total Walkthrough Distance: 3.55 km
Percent of Walk Line Distance [100m segments] with Live Beetles: 11.3 %
Number Pixels Surveyed: 2
Pixel Data - Attack Percentages by Yr. of Attack:

- (2018) 0.00 %
- (2017) 0.00 %
- (2016) 0.00%

Pixel Data - Percent Spruce: 49.26 %
Sanitation and Salvage Harvest Rate: 0.00
Monitor - Aerial

Mapping Date: 2/08/2019

Mapper: Niki Rosenthal

Data Source: BCGW

N W E S

Scale: 1:10,000

0 120 240 360 480 600
Meters

This map is georeferenced
Coordinate System: NAD 1983 BC Environment Albers