Access: South Puggins road runs through the center of the polygon.



Operability – Flat with a south east facing slope of 10-15 % in places.

Resource Management Concerns – Wet pockets along the south east boundary. Moose and Deer tracks.

Vigour of Beetle population – 1 year cycle on the trees with current attack.

Other Factors – Some larger spruce in the northern half of the polygon.

SPECTRUM RESOURCE GROUP INC

Dawson Creek
Sx Beetle Probe

Block 84909
Final Map

Legend

- Block of Interest
- Dead Attack
- Live Attack
- No Attack
- Surrounding Blocks
- Pixels
- Tracks
- Roads
- Roads - Condition Unknown
- Contours_50k
- Lakes/Rivers
- Streams

FH198240003

Date Surveyed: January 20, 21, 2018
Surveyors: Aiden Wichnewski, Joel Neufeld
Area Surveyed: 33.9 Ha
Total Walkthrough Distance: 3.3 km
Percent of Walk Line Distance [100m segments] with Live Beetles: 3 %
Number Pixels Surveyed: 1
Pixel Data - Attack Percentages by Yr. of Attack:

- (2018) 0.00 %
- (2017) 0.00 %
- (2016) 2.47 %

Pixel Data - Percent Spruce: 64.23 %
Sanitation and Salvage Harvest Rate: 39.62
Monitor – larger diameter spruce, especially in the northern half of the polygon.

Mapping Date: 1/31/2019

Mapper: Niki Rosenthal

Data Source: BCGW

N W E S

Scale: 1:10,000

0 120 240 360 480 600
Meters

This map is georeferenced
Coordinate System: NAD 1983 BC Environment Albers