SENECA ENTERPRISES LTD.
PO BOX 1902, PRINCE GEORGE, BC, V2L 5E3
Phone: (250) 561-0890, Fax: (250) 564-3275

SPRUCE BARK BEETLE REPORT
FH17DPG218

STAR PROBE# **2016-CLE-0053** 503

NUMBER OF CODE 1-4 ATTACK 0

PROBE LINE NO

SUMMARY OF CURRENT INFESTATION **NO ATTACK**

Star Probe had no current signs of attack.. Site extremely steep with 60% Spruce.

ACCESS

From Truck, adjacent to mainline. Steep walk up within site.

SITE FEATURES (Topography, Terrain, Timber Types, Age)

Sparse open stand. Steep slopes to site 60+%

SIZE, BOUNDARY and PATTERN OF INFESTATION

No current attack at site.

INCIDENCE AND SEVERITY OF ATTACK

No current attack.

RISK OF BEETLE SPREAD and SURROUNDING SITES

Sparse spruce stand, no current attack, very steep.

ACCESS, OPERABILITY and INTEGRATED RESOURCE MGMT ISSUES

Up steep slope to site.

RECOMMENDATIONS

OPTION 1 **NO ACTION**






plot 503
N 100m
06/11/16
Ridge
W 100m
100m E
39m
road
100m
S