SENECA ENTERPRISES LTD.
PO BOX 1902, PRINCE GEORGE, BC, V2L 5E3
Phone: (250) 561-0890, Fax: (250) 564-3275

SPRUCE BARK BEETLE REPORT
FH17DPG218

STAR PROBE# **2016-CLE-0055** 505

NUMBER OF CODE 1-4 ATTACK 0

PROBE LINE NO

SUMMARY OF CURRENT INFESTATION **NO ATTACK**

Star Probe had no current signs of attack, one code 5 attack. Siteextremely steep with 60% Spruce.

ACCESS

From Truck walk 1.4km @ 128degrees. Steep walk up to site, some thin patches of alder in South

SITE FEATURES (Topography, Terrain, Timber Types, Age)

Sparse open stand. Steep slopes to site 60+%

SIZE, BOUNDARY and PATTERN OF INFESTATION

No current attack at site, one code 5, no other attack noticed

INCIDENCE AND SEVERITY OF ATTACK

No current attack.

RISK OF BEETLE SPREAD and SURROUNDING SITES

Sparse spruce stand, no current attack, very steep.

ACCESS, OPERABILITY and INTEGRATED RESOURCE MGMT ISSUES

Up steep slope to site.

RECOMMENDATIONS

OPTION 1 **NO ACTION**

OPTION 2




Plot 505
N
100m
W
100m
72m
E
160m
5
70m
Band of Alder
S
100m
Megan Austey
Mark Videgain
METRIC FIELD