SENECA ENTERPRISES LTD.
PO BOX 1902, PRINCE GEORGE, BC, V2L 5E3
Phone: (250) 561-0890, Fax: (250) 564-3275

SPRUCE BARK BEETLE REPORT
FH17DPG218

STAR PROBE# **2016-CLE-0059** 509

NUMBER OF CODE 1-4 ATTACK 0

PROBE LINE NO

SUMMARY OF CURRENT INFESTATION **NO ATTACK**

Star Probe had no signs of attack. Site had some severe blowdown just north of site 2016-CLE-0059 and some evidence of old beetle.

ACCESS

From Truck walk 800m @ 63degrees. Steep walk up to site, some thin patches of alder

SITE FEATURES (Topography, Terrain, Timber Types, Age)

Sparse open stand. Steep slopes to site 0-40%

SIZE, BOUNDARY and PATTERN OF INFESTATION

No attack at site, some older blowdown just north of site 2016-CLE-0059

INCIDENCE AND SEVERITY OF ATTACK

No attack.

RISK OF BEETLE SPREAD and SURROUNDING SITES

Sparse spruce stand, minimal risk of spread.

ACCESS, OPERABILITY and INTEGRATED RESOURCE MGMT ISSUES

Up steep slope to site.

RECOMMENDATIONS

OPTION 1 **NO ACTION**

OPTION 2



Plot 510 06/11/16



Megan Anstey Mark Videgain

METRIC FIELD

R.D. PENHALL LTD. MADE IN VANCOUVER, CANADA DURSBAK WATERPROOF

Plot 509



Megan Anstey Mark Videgain

METRIC FIELD