

CK-2010

BLUE MTN TWO 2.5km

2017 Inspection

CBR iPad Offline Ver 0.26



CBR Data

Latitude	Longitude
49°14'31.49"	-122°28'52"
Crossing Name	Martyn Creek East Fork
FSR #	5913
Branch #	2
Road Name	BLUE MTN TWO
User km	2.5
Current Load Rating (tonnes)	
Structure Class	Temporary Bridge
Portable	N
Superstructure	Other
Deck Type	Other
Abutment Left	Other
Abutment Right	Other
Spans	1
Total Length (m)	0
Deck Width (m)	6

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5481603.6
Accuracy (m)	

0

Inspection

Date of Inspection 2017-07-20 9:31:14 AM

Inspector Name Tyson Miller

Inspector Comments

Structure is a ford

Recommended Next Inspection Year - inspect with regular road inspections

Inspection Company MFLNRO

P.Eng Comments

Structure is a ford, inspect with regular road inspections. Send in record drawings of structure. BCL-625 or 64 tonnes.



30/08/2017

P.Eng Seal

CK-2010

BLUE MTN TWO 2.5km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition NA

Posted Load Rating Not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2010

BLUE MTN TWO 2.5km

2017 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)		Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Looking downstream



Looking upstream



Approach from Left Bank when facing downstream

CK-2010

BLUE MTN TWO 2.5km

2017 Inspection



Outlet