

CK-2029

CHEHALIS 39.9km

2017 Inspection

CBR iPad Offline Ver 0.26



CBR Data

Latitude	Longitude
49°30'25.4"	-122°1'46.9"
Crossing Name	Statlu Lake Creek
FSR #	8241
Branch #	1
Road Name	CHEHALIS
User km	39.9
Current Load Rating (tonnes)	
Structure Class	Temporary Bridge
Portable	N
Superstructure	Timber - untreated stringers
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	18.1
Deck Width (m)	4.88

Updated Data

Latitude	Longitude
49°30'31.13"	-122°1'47.63"
HD Diff. (m)	177.7
Accuracy (m)	5
Bridge deactivated	
NA	
NA	
NA	
NA	
NA	
NA	
NA	

Inspection

Date of Inspection 2017-06-20 10:55:15 AM

Recommended Next Inspection Year NA

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

No further inspections required

P.Eng Comments

Bridge deactivated, no further inspections required.



06/09/2017

P.Eng Seal