

CK-2509

STATLU 11.2km

2019 Inspection



CBR iPad Offline Ver 0.28

CBR Data

Latitude	Longitude
49°24'4.79"	-122°5'58.6"
Crossing Name	unknown
FSR #	8241
Branch #	2
Road Name	STATLU
User km	11.2
Current Load Rating (tonnes)	63
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Sill -Temporary Materials
Abutment Right	Sill -Temporary Materials
Spans	1
Total Length (m)	7
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°24'4.48"	-122°5'58.93"
HD Diff. (m)	11.8
Accuracy (m)	5

NA

Inspection

Date of Inspection 2019-03-28 11:58:42 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year NA


Inspection Company MFLNRO

Inspector Comments

Bridge deactivated, no further inspections required

P.Eng Comments

Bridge removed, no further inspections required.



P.Eng Seal



Approach from Left Bank when facing downstream



Upstream Profile



Approach from Left Bank when facing downstream



Stringers