

CK-2441

FIFTEEN MILE 1.5km

2020 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude 49°28'28.49" Longitude -121°15'39.4"

Crossing Name Fifteen Mile Creek

FSR # 10452 Branch # 1

Road Name FIFTEEN MILE

User km 1.5

Previous Load Rating (tonnes) 40

Structure Class Temporary Bridge

Portable N

Superstructure Rail Car

Deck Type Timber - Untreated

Abutment Left Sill -Temporary Materials

Abutment Right Sill -Temporary Materials

Spans 1

Total Length (m) 16

Deck Width (m) 5.6

Updated Data

Latitude Longitude

HD Diff. (m) 623.3 Accuracy (m) 5

0 tonnes

Inspection

Date of Inspection April 21, 2020

Recommended Next Inspection Year 2022

Inspector Name T. Miller

Inspection Company FLNRORD

S

Inspector Comments

No vehicle access to structure. No further inspections required until road opened

P.Eng Comments

There's no longer vehicle access to this structure. Structure condemned until an inspection is required or the road is opened. The bridge is condemned (0 tonnes load rating) until another inspection can be completed.





2020 Inspection

FIFTEEN MILE 1.5km

CK-2441

CBR iPad Offline Ver 0.31



No vehicle access as road is now completely brushed in