

CK-2250
CK-2250

SPUZZUM 16000 5.9km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°41'1.39" Longitude -121°38'31.7"

Site Status Barricaded/Closed

Insp. Status Do Not Inspect

Crossing Name Side Creek

FSR # 8128 Branch # 7

Road Name SPUZZUM 16000

User km 5.9

Previous Load Rating (tonnes) 0

Structure Class Temporary Bridge

Portable N

Superstructure Steel I-beam

Deck Type Timber - Untreated

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 11

Deck Width (m) 3.5

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5530766.6 Accuracy (m)

Inspection

Date of Inspection 2022-11-02 1:13:42 PM

Inspector Name Cameron VandenBrink, EIT

Recommended Next Inspection

Inspection Company Chartwell Resource Group Ltd

Inspector Comments Serial/ID Plate

Does not appear to have guard rail. Could not land helicopter within 2km of site due to vegetation height.

P.Eng Comments

Load Rated by: MoF, M.Lowe, RPF, PEng, February 16, 2023
Load Rating: 0 Tonnes GVW
Next Inspection: September 1, 2025
Comments: No access to site. Reinspect when next active.



PERMIT TO
PRACTICE: 1003022

CK-2250
CK-2250

SPUZZUM 16000 5.9km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2250
CK-2250

SPUZZUM 16000 5.9km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

Pier Deck

CK-2250
CK-2250

SPUZZUM 16000 5.9km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2250
CK-2250

SPUZZUM 16000 5.9km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)

High Water ☐

Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance

Ic ☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



2022 Inspection

CBR iPad Offline Ver 0.36

SPUZZUM 16000 5.9km

CK-2250
CK-2250



Aerial



Aerial



Aerial