




Sparks Lake
K21001
REHAB MAP
B4
Page 8 of 33
Map Date: June 13, 2022

Perimeter Date: 2022-06-20
Headscale: 10000:1

2 OPS Point (PTType)

PTType

- On-Site Check Area
- Grassland Wood (GWS)
- Fence Damage - Point (FD)
- Pull Back (PB)
- Historic Draw (HD)
- Safety Zone (SZ)
- Slash / Burn Pile / Hazard (SBP)
- Steep Slope > 30% (SS)
- Stream Crossing (SC)
- Unimproved
- Other Rehab Treatment Type
- Pull Back (PB)
- Rehabilitation Measure Completed
- Road - Modified Existing
- Rehab - Requires Field Verification

Rehab Line [Status]

Status Line

- Rehab - Requires Field Verification
- Rehab - Requires Field Verification
- Rehab - Requires Field Verification

Rehab: 1:24 Grid

Rehab Work Zone Boundaries

- Trail
- Trail
- Trail
- Forest Service Road
- Road Permit
- Road
- Mountain
- Stream - Interim
- Lake - Interim
- Wetland
- Freshwater
- Recreation Site
- Archaeological Site
- Fence
- Stock Trail
- Fish - Observed
- Fish - Observed
- Fish Distribution
- Fire Perimeter
- Lake - Interim
- Lake - Interim
- BC Park, Protected Area, Eco Region
- Private

This map may contain
CONFIDENTIAL
information for INTERNAL
use only

Disclaimer:
This map was prepared by the Ministry of Forests, Land, Natural Resources Operations and Rural Development (MLNRO) for the purpose of providing information to the public. It is not intended to be used for any other purpose. The Ministry of Forests, Land, Natural Resources Operations and Rural Development (MLNRO) is not responsible for any errors or omissions in this map. The Ministry of Forests, Land, Natural Resources Operations and Rural Development (MLNRO) is not responsible for any damages or losses resulting from the use of this map. The Ministry of Forests, Land, Natural Resources Operations and Rural Development (MLNRO) is not responsible for any damages or losses resulting from the use of this map.

Map Date: 2022-06-20
Headscale: 10000:1

Ministry of Forests, Land, Natural Resources Operations and Rural Development

SWIMM