


Sparks Lake

K21001

REHAB MAP

C3


Page 12 of 33

Map Date: June 13, 2022

Perimeter Date: 2021-08-20
Hectares: 89626.7HA

2 OPS Point [PTType]
PTType
- OPS Cleared Area
- Cross Ditch - Repair (CDR)
- Culvert - Clean/Repair Culvert (CC)
- Fence No Damaged - Point (FND)
- Safety Zone (SZ)
- Steep Slope >35% (SS)
- Stream Crossing (SC)
- Unassigned
- Other Rehab Treatment Type
- Pull Back (PB)
- Fireguard Machine Completed
- Road - Modified Existing
- Rehab - Requires Field Verification
- Fire Perimeter

- Rehab 10k Grid
- Rehab Work Zone Boundaries
- Trail
- Trail
- Forest Service Road
- Road Permit
- Road
- Mountain
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Campsite
- Radio Tower
- Groudwater Well
- Archaeological Site
- Water Development
- Fence
- Stock Trail
- Fish - Observed
- Fish - Observed
- Fire Perimeter
- Lake
- Lake - Intermittent
- Indian Reserve
- BC Park, Protected Area, Eco Reserve
- Private
- Crown Federal



This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Wildfire perimeters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems nightly to the public map. Wildfire data may not reflect the current fire situation, and therefore should only be used for reference purposes.

Wildfire data from the incident is updated when practicable and the occurrence of individual fire updates will vary . The information is intended for general purposes only and should not be relied on as accurate because fires are dynamic and circumstances may change quickly. The levels of current fire activity within the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created by: plambkin

BRITISH COLUMBIA
Ministry of Forests, Lands, Natural Resource Operations and Rural Development