Sparks Lake

K21001

REHAB MAP

D3

Map Date: June 13, 2022

Perimeter Date: 2021-08-30
Hectares: 89626.7 HA

2 OPS Point [PTType]
PTType
- OPS Cleared Area
- Decked Wood (DW)
- Pull Back (PB)
- Restore Draw (RD)
- Safety Zone (SZ)
- Steep Slope >30% (SS)
- Unassigned

Other Rehab Treatment Type
- Pull Back (PB)
- Fireguard Machine Completed
- Road - Modified Existing
- Rehab - Requires Field Verification

Rehab Line [Status]
Status Line
- Rehab - Requires Field Verification
- Fire Perimeter

- Rehab 10k Grid
- Rehab Work Zone Boundaries
- Trail
- Trail
- Road Permit
- Road
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Failing or Gullied Terrain
- Potentially Unstable Terrain
- Climate Station
- Water Development
- Fence
- Stock Trail
- Aquatic
- Fish - Observed
- Fish - Observed
- Fire Perimeter
- Lake
- Lake - Intermittent
- Private

This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Operational parameters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems on a regular basis. This map is intended to be a snapshot of the current fire situation, and therefore should only be used for reference purposes.

Wildfire data from the incident is updated when practicable and the occurrence of individual fire updates may lag. This map is intended for internal use and planning purposes only and should not be relied on as accurate. Fire perimeters and fire locations may change within short change events. The levels of current fire activity and the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created By: jcamber

Ministry of Forests, Lands, Natural Resource Operations and Rural Development