




Sparks Lake

K21001

REHAB MAP

D5

Page 20 of 33

Map Date: June 13, 2022

Perimeter Date: 2022-06-20

Revised: 06/20/2022

- Conduit - Cleanstream Culvert (CC)
- Debris Road (DR)
- Pull Back (PB)
- Restore Draw (RD)
- Safety Zone (SZ)
- Safety Zone - No Hazard (SNH)
- Safety Zone - High Hazard (SHH)
- Other Rehabilitation Type
- Pull Back (PB)
- Restoration Material Compacted
- Road - Modified Existing
- Node - Requires Field Verification
- Fire Perimeter

- Round 124 Grid
- Rehab Work Zone Boundaries
- Trail
- Trail
- Private Service Road
- Road Permit
- Road
- Mountain
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Freshwater
- Filling or Gullied Terrain
- Unstable Terrain
- Potentially Unstable Terrain
- Dam
- Archaeological Site
- Fish - Observed
- Fire Perimeter
- Lake - Intermittent
- BC Park, Protected Area, Eco Restoration

This map may contain
CONFIDENTIAL
information for INTERNAL
use only

Disclaimer:
Information is provided for general information only. It is not intended to be used for legal or financial purposes. The user assumes all responsibility for the use of the information. The user acknowledges that the information is provided for general information only and is not intended to be used for legal or financial purposes. The user acknowledges that the information is provided for general information only and is not intended to be used for legal or financial purposes.

Map Date: June 13, 2022

Revised: 06/20/2022

Created by: [Name]