121°0'0"W

120°55'0"W

51°0'0"N

C1

C2

C3

D1

D2

D3

E2

Safety Zone

Restore Draw

Safety Zone

Restore Draw

Safety Zone

Restore Draw

Safety Zone

Restore Draw

Decked Wood

Restore Draw

Cross Ditch - Install

Cross Ditch - Install

Decked Wood

Decked Wood

MS-482-C-M-VW

Sparks Lake

Sparks Lake

Sparks Lake

N

Sparks Lake

K21001


REHAB MAP

D2

Map Date: June 13, 2022

Perimeter Date: 2021-08-30
Hectares: 89626.7 HA

- Cattle Guard No Damage (CGND)
- Cross Ditch - Install (CDI)
- Decked Wood (DW)
- Gate Damage (GD)
- Restore Draw (RD)
- Safety Zone (SZ)
- Stream Crossing (SC)
- Other Rehab Treatment Type
- Pull Back (PB)
- Fireguard Machine Completed
- Road - Modified Existing
- Rehab 10k Grid
- Rehab Work Zone Boundaries
- Fire Perimeter
- Trail
- Trail
- Trail
- Trails
- Road Permit
- Road
- Pipeline
- Pipeline
- Transmission Line
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Freshwater
- Rehab 10k Grid
- Rehab Work Zone Boundaries
- Lake
- Lake - Intermittent
- Private



This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Wildfire perimeters for the current fire season, including wildfire perimeters tracked from third parties (contract sources). The data is refreshed from operational systems daily. The wildfire perimeters are subject to change and may not be final to the wildfire. Wildfire data may not be fit for use for reference purposes.

Wildfire data from the incident is updated when practicable and the occurrence of individual fire updates may vary. The wildfire perimeters are for internal purposes only and should not be relied on as accurate because fires are dynamic and circumstances may change rapidly. The accuracy of the data may reflect the mapping technology and methods used.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created By: jstamton

Ministry of Forests, Lands, Natural Resource Operations and Rural Development