120°40'0"W

120°35'0"W

C1

C4

C5

D1

D3

D4

D5

E3

E4

N 54°47'30"

N 54°45'0"

# Sparks Lake

**K21001**

REHAB MAP

D4



Map Date: June 13, 2022

**Perimeter Date:** 2021-08-30
**Hectares:** 89626.7 HA

- Decked Wood (DW)
- Ditch - Clean/Repair (CD)
- Pull Back (PB)
- Restore Draw (RD)
- Safety Zone (SZ)
- Slash / Burn Pile / Hazard (SBP)
- Steep Slope >35% (SS)
- Stream Crossing (SC)
- Unassigned
- Other Rehab Treatment Type
- Pull Back (PB)
- Frequent Machine Completed
- Road - Modified Existing
- Rehab - Requires Field Verification
- Rehab 10k Grid
- Rehab Work Zone Boundaries
- Fire Perimeter

- BC Park, Protected Area, Eco Reserve
- Trail
- Forest Service Road
- Road Permit
- Road
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Rehab 10k Grid
- Rehab Work Zone Boundaries
- Lake
- Lake - Intermittent
- Private



This map may contain CONFIDENTIAL information: for INTERNAL use only

**Disclaimer:**
Wildfire perimeters for the current fire season, including the Fire Perimeter, are updated daily from wildfire mapping sources. The data is refreshed from operational systems nightly to the public map. Wildfire data may not reflect accurate fire boundaries and therefore should only be used for reference purposes.

Wildfire data from the incident is updated when perimeters and the occurrence of individual fire spotted outside the perimeter is received. Fire perimeters are only and should not be relied on as accurate measures of fire size, shape, location, complexity or change quickly. The levels of current fire activity within the mapped fire perimeters can vary widely.

**Data Sources and Notes:**

**Projection:** NAD 1983 BC Environment Albers
**Created by:** jcarrion

Ministry of Forests, Lands, Natural Resource Operations and Rural Development

Document Path: Y:\Fire\Seasons\wk2021\Kamloops\K21001\K21001_Rehab_Imagery_36x48L.mxd