120°50'0"W

120°45'0"W

50°5'0"N

F2

F3

F4

G2

G3

CARABINE HILL

EAGLE HILL

MT UREN MT

MS 462 C-M VW

Equipment

Cross Ditch - Repair

Cross Ditch - Repair

Cross Ditch - Repair

Cross Ditch - Repair

Cross Ditch - Repair

Cross Ditch - Repair

A3

A4

A5

A6

B1

B2

B3

Dry Seed

Dry Seed

Dry Seed

Dry Seed

Dry Seed

Fence Damage

Burned Corduroy

Cattle Guard Damage

Cattle Guard Damage

Equipment

Equipment

Equipment

Green South

Sparks Lake

Sulphur Lake

Sulphur Lake

Sulphur Lake

Sparks Lake

Quilchena Creek

Quilchena Creek

N

## Sparks Lake

**K21001**

REHAB MAP

F3



Map Date: June 13, 2022

**Perimeter Date:** 2021-08-30
**Hectares:** 89626.7 HA


- Cattle Guard Damage (CGD)
- Cross Ditch - Install (CDI)
- Cross Ditch - Repair (CDR)
- Culvert - Clean/Repair Culvert (CC)
- Decked Wood (DW)
- Dry Seed (DS)
- Fence Damage - Point (FD)
- Recontour (RC)
- Restore Draw (RD)
- Staging Area (SA)
- Steep Slope >35% (SS)
- Stream Crossing (SC)
- Sump (SP)
- Unassigned
- Hazard (H)
- Other Rehab Treatment Type
- Pull Back (PB)
- Fireguard Machine Completed
- Road - Modified Existing
- Rehab - Requires Field Verification

**Rehab Line [Status]**

**Status Line**

- Rehab - Requires Field Verification
- Rehab 10k Grid
- Rehab Work Zone Boundaries
- Fire Perimeter

- Wildlife Management Area
- Trail
- Trail
- Forest Service Road
- Road Permit
- Road
- Transmission Line
- Mountain
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Freshwater
- Rehab 10k Grid
- Rehab Work Zone Boundaries
- Lake
- Lake - Intermittent
- Private



This map may contain CONFIDENTIAL information: for INTERNAL use only

**Disclaimer:**
Rehab perimeters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems on a daily basis. The information is intended for use during the current fire situation, and therefore should only be used for reference purposes.

Wildfire data from the incident is updated when information is received from ground crews and fire spotters and flights. The information is intended for general purposes only, and should not be used as an accurate measurement. Fire and rehab perimeters are subject to change quickly. The levels of current fire activity within the mapped fire perimeters can vary widely.

**Data Sources and Notes:**

**Projection:** NAD 1983 BC Environment Albers
**Created By:** jsarmon

Ministry of Forests, Lands, Natural Resource Operations and Rural Development

Document Path: V:\Fire\Response\Work\2021\Admin\pyrt\FK21001\FK21001_Rehab_Imagery_Mar06.mxd