





- Cable Guard No Damage (CGND)
- Cross Ditch - Install (CDI)
- Decked Wood (DW)
- Gate Damage (GD)
- Stream Crossing (SC)
- Other Rehab Treatment Type
- Full Back (FB)
- Repaired Stream Component
- Road - Modified Existing
- Stockpile Storage
- Tree Perimeter

- Trail
- Trail
- Road Permit
- Pipeline
- Transmission Line
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Pipeline
- Pipeline
- Falling or Gullied Terrain
- Interpretive Forest/Recreation Area
- Pipeline
- Transmission Line
- Transmission Line
- Radio Tower
- Groundwater Well
- Archaeological Site
- Water Development
- Fence
- Stock Trail
- Fish - Observed
- Fish Distribution
- Lake
- Lake - Intermittent
- Private



This map may contain
information for INTERNAL
use only

Disclaimer:
Map data is derived from a variety of sources, including
aerial photography, ground surveys, and other data. The
accuracy of the data is not guaranteed. The map is for
informational purposes only and should not be used for
decision-making without consulting the appropriate
authorities. The map is subject to change without
notice. The map is provided as a service and is not
warranted. The map is provided as a service and is not
warranted. The map is provided as a service and is not
warranted.

Map Date: 2022-08-20
Map Date: 2022-08-20