




- Cleared Area (CA)
- Decayed Wood (DW)
- Pile Rock (PR)
- Unvegetated
- Other Road Treatment Type
- Pile Rock (PR)
- Forest Mosaic Overlay
- Road Modified Crossing
- Dist_100_36455
- Point - Requires Field Verification
- Fire Perimeter
- Forest Service Road
- Road Permit
- Road
- Mountain
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Freshwater
- Fading or Cultured Terrain
- Unstable Terrain
- Potentially Unstable Terrain
- Lodge
- Campsite
- Dam
- Fence
- Stock Trail
- Fish - Spawning
- Fish - Observed
- Fish - Observed
- Fish Distribution
- Lake
- Lake - Intermittent
- BC Park, Protected Area, Ecol Res

5130750

5130750