Tremont Creek

K21849

REHAB MAP

B3

Map Date: July 14, 2022

Perimeter Date: 2021-08-20
Hectares: 62523.6HA

120°55'0"W
120°50'0"W
50°40'0"N
N
MOUNT SAVONA PARK
Zone 5
Zone T1
Zone T2
Zone 4
Zone 3
Zone 2
TUNKWA PARK
Kamloops Lake
Leighton Lake
Leighton
Leighton Airport
Sperm Lake
Fence - MS 462 C-M VW
Fence Damaged
Fence No Damage
Cross Ditch - Repair
Cross Ditch - Install
Cross Ditch
Should Cross Ditch
Stream Crossing
Corded Creek
Restore Draw
Steep Slope
Steep Ground Water Bar
Safety Zone
Cattle Guard No Damage
Fence Damage
Decked Wood
Bunched Wood
Access to Decked Wood
Enbridge Vent
AG18 Helispot
AH24
SH12
RD-5-1
RD-5-2
RD-5-3
RD-5-4
RD-5-5
RD-5-6
RD-5-7
RD-5-95
RD-5-96
RD-5-97
RD-5-98
RD-5-99
RD-5-11
RD-T1-1
RD-T1-2
RD-T1-3
RD-T1-4
MG-5-7
MG-5-9
MG-5-10
MG-5-11
MG-5-12
MG-5-13
MG-5-14
MG-5-15
MG-5-16
MG-5-17
MG-5-18
MG-5-19
MG-5-20
MG-5-21
MG-5-22
MG-5-23
MG-5-24
MG-5-25
MG-5-26
MG-5-80
MG-5-81
MG-5-90
MG-T1-1
MG-T1-2
MG-T1-3
MG-T1-4
MG-T2-1
MG-T2-2

2 QPS Point [PTType]

PTType

- QPS Cleared Area
- Water Source
- Hazard
- Cattle Guard No Damage (CGND)
- Cross Ditch - Install (CDI)
- Cross Ditch - Repair (CDR)
- Culvert - Clean/Repair Culvert (CC)
- Decked Wood (DW)
- Fence Damage - Point (FD)
- Fence No Damaged - Point (FND)
- Other Rehab Treatment Type
- Restore Draw (RD)
- Safety Zone (SZ)
- Steep Slope >35% (SS)
- Stream Crossing (SC)
- No Treatment - Point (NA)
- Unassigned
- Water Bar (WB)

- Other Rehab Treatment Type
- Pull Back (PB)
- Frequent Machine Completed
- Road - Modified Existing
- Rehab - Requires Field Verification
- Rehab - Requires Field Verification
- Fire Perimeter

- 10k Grid
- Rehab Work Zone Boundary
- Trail
- Trail
- Forest Service Road
- Road Permit
- Main Road
- Road
- Pipeline
- Pipeline
- Transmission Lines
- Transmission Line
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Failing or Gullied Terrain
- Campsite
- Pipeline
- Transmission Lines
- Transmission Line
- Groundwater Well
- Dam
- Archaeological Site
- Legacy Archaeological Site
- Fence
- Stock Trail
- Fish - Observed
- Lake
- Lake - Intermittent
- BC Park, Protected Area, Eco Reserve

Index Map

This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Wildfire perimeters for the current fire season, including the most recent perimeters, are received from various sources. The data is refreshed from operational systems nightly to the public map. Wildfire data may not reflect all fires within the province and therefore should only be used for reference purposes.

Wildfire data from the incident is updated when practicable and the occurrence of individual fire updates will vary. The information is intended for general reference purposes only and the accuracy of the data is not guaranteed because fires are dynamic and circumstances may change quickly. Some fires may not be actively worked and the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created by: jcamber

Ministry of Forests, Lands, Natural Resource Operations and Rural Development

Document Path: Y:\FireSeason\Work\2021\Kamloops\K21849\K21849_Rehab_36x48L.mxd