Tremont Creek

K21849

REHAB MAP

C4

Map Date: June 14, 2022

Perimeter Date: 2021-08-20
Hectares: 62523.6HA

120°45'0"W

120°40'0"W

50°35'0"N

50°30'0"N

N

Zone 5

Zone 7

Zone 6

Check Wet
Check
Wet Spot

MG-6-10

MG-6-10

MG-6-10

Corduroy
on Stream

Bridge Out

RD-6-7

Corduroy

Corduroy
on road

Cross ditch with
large rocks,
not passable

Stream
Crossing
needs rehab

RD-6-6

MS 462 C-M VW

Corduroy

Decked Wood

Water Bar

RD-6-8

Water Bar

Water
Bar

Water
Bar

Pull
Back

Decked
Wood

Decked
Wood

Decked
Wood

MG-6-19

MG-6-20

RD-6-9

RD-6-9

Decked
Wood

Decked
Wood

AV11 Helispot

RD-6-10

MG-6-12

Pull Back

RD-6-11

Water Bar

Water Bar

Pull Back

MG-6-13

Decked
Wood

Cross Ditch
- Install

Cross Ditch
- Repair

Water Bar

MG-6-13

Decked Wood

Water Bar

Fence No
Damage

RD-6-12

Water Bar

Index Map

This map may contain CONFIDENTIAL information: for INTERNAL use only

Disclaimer:
Wildfire perimeters for the current fire season, including both active and inactive fires, are supplied from various sources and may be updated periodically throughout the day/night to the public map. Wildfire data may not reflect the current fire situation, and therefore should only be used as a reference source.

Wildfire data from this location is updated when practicable and the occurrence of individual fire updates may vary. Wildfire data is provided for reference purposes only and should not be relied on as accurate because fires are dynamic and circumstances may change quickly. The location of wildfire activity within the mapped fire perimeters can vary widely.

Data Sources and Notes:

Projection: NAD 1983 BC Environment Albers
Created by: jmorrison

Ministry of
Forests, Lands, Natural
Resource Operations
and Rural Development

2 OPS Point [PTType]
PTType
- OPS Cleared Area
- Hazard
- Cross Ditch - Install (CDI)
- Cross Ditch - Repair (CDR)
- Decked Wood (DW)
- Fence No Damaged - Point (FND)
- Other Rehab Treatment Type
- Pull Back (PB)
- Stream Crossing (SC)
- Unassigned
- Water Bar (WB)

Other Rehab Treatment Type
Pull Back (PB)
Frequent Machine Completed
Road - Modified Existing
Rehab - Requires Field Verification
Rehab - Requires Field Verification
Fire Perimeter

10k Grid
Rehab Work Zone Boundary
Trail
Trail
Trail
Trails
Forest Service Road
Road Permit
Main Road
Road
Stream
Stream - Intermittent
Lake
Lake - Intermittent
Wetland
Freshwater
Failing or Gullied Terrain
Unstable Terrain
Potentially Unstable Terrain
Campsite
InterpretiveForestRecreationReserve
Groundwater Well
Dam
Archaeological Site
Water Development
Fence
Stock Trail
Fish - Observed
Fish - Observed
Lake
Lake - Intermittent
Private
Private

Document Path: Y:\FIA\Data\REHA\2021\Kamloops\KAM\21849\21849_Rehab_Sheet6c.mxd