# Tremont Creek

**K21849**

REHAB MAP

**Zone 2 - B1**

Map Date: February 21, 2022

**Perimeter Date:** 2021-08-20
**Hectares:** 62523.6HA

GLOSSY MTN

MS 462 C-M VW

121°10'0"W

121°5'0"W

50°40'0"N

50°35'0"N

N

Safety Zone
RDS
Bunched Fd
Track 1
46% 10m
Restore Draw
42% 15m
Track 34
40% 15m
Track 2
Safe Zone
Restore Draw
Track 33
Pile And Burn Slash Here
Stream Crossing No Machine Or Atv Access
Safety Zone
Decked Wood
Decked Wood
Track 26
RD
Needs Repair
Track 25
Safety Zone
Track 29
Fuel Hazard
Bunched Wood
Fuel Hazard
40% 20m
47% 30m
45% 20m
44% 20m
Track 49
Ditch - Clean/Repair
Stream Crossing
Restore Draw
Restore Draw
Stream Crossing
Track 49
39.10m
Restore Draw
Restore Draw
Safety Zone
Track 30
Stream Crossing
Track 31
Glossy
Decked Wood
Track 38
Restore Draw
Critical Site
Track 37
Restore Draw
Restore Draw
Track 32
Restore Draw
Track 35
Restore Draw
Track 36
RD
Critical Site Rehab Draw
46% 50m
Track 32
38% 15m
Track 39
Restore Draw
Track 40
Safety Zone
Stream Crossing
Safety Zone
Critical Site
Drainage to rehab
Drainage to rehab
Restore Draw
Track 41
Restore Draw
Bunched Wood
Track 48
40% 15m
Restore Draw
Placemark 120
39% 15m
Track 42
Track 44
Track 45
Track 46
Track 47
Track 47
Track 46
No Guard Built Old Road
Line 2
Fence Unburned
Track 19
Access Should Be Closed As It Was Before
Open Up
Cross Ditch - Install
Access Should Be Closed As It Was Before
Track 5
Woods Creek
20 Logs
Clean Stream Below Rd
Bunched Sx Along Rd
Bladder
Tremont
Safety Zone
Restore Draw
Placemark 24
Track 6
Restore Draw
Restore Draw
35% 15m
Cross Ditch - Install
Restore Draw
Cross Ditch - Install
RD
Cross Ditch Install
Cross Ditch - Install
57% 10m
Track 20
Fence Damage
Track 14
Track 8
Track 21
Placemark 15
Bunched Pine
Track 18
Track 17
Track 16
Cross Ditch Install
Track 15
Placemark 47
Placemark 50
Restore Draw
Placemark 40
Track 10
Placemark 41
Track 49
Ditch - Clean/Repair
Stream Crossing
Restore Draw
Restore Draw
Stream Crossing
Track 49
39.10m
Restore Draw
Restore Draw
Safety Zone
Track 30
Stream Crossing
Track 31
Glossy
Decked Wood
Track 38
Restore Draw
Critical Site
Track 37
Restore Draw
Restore Draw
Track 32
Restore Draw
Track 35
Restore Draw
Track 36
RD
Critical Site Rehab Draw
46% 50m
Track 32
38% 15m
Track 39
Restore Draw
Track 40
Safety Zone
Stream Crossing
Safety Zone
Critical Site
Drainage to rehab
Drainage to rehab
Restore Draw
Track 41
Restore Draw
Bunched Wood
Track 48
40% 15m
Restore Draw
Placemark 120
39% 15m
Track 42
Track 44
Track 45
Track 46
Track 47
Track 47
Track 46
No Guard Built Old Road
Line 2
Fence Unburned
Track 19
Access Should Be Closed As It Was Before
Open Up
Cross Ditch - Install
Access Should Be Closed As It Was Before
Track 5
Woods Creek
20 Logs
Clean Stream Below Rd
Bunched Sx Along Rd
Bladder
Tremont
Safety Zone
Restore Draw
Placemark 24
Track 6
Restore Draw
Restore Draw
35% 15m
Cross Ditch - Install
Restore Draw
Cross Ditch - Install
RD
Cross Ditch Install
Cross Ditch - Install
57% 10m
Track 20
Fence Damage
Track 14
Track 8
Track 21
Placemark 15
Bunched Pine
Track 18
Track 17
Track 16
Cross Ditch Install
Track 15
Placemark 47
Placemark 50
Restore Draw
Placemark 40
Track 10
Placemark 41

## 2 QPS Point [PTType]

**PTType**

- QPS Cleared Area
- Water Source
- Cross Ditch - Install (CDI)
- Cross Ditch - Repair (CDR)
- Decked Wood (DW)
- Ditch - Clean/Repair (CD)
- Fence Damage - Point (FD)
- Fence No Damaged - Point (FND)
- Pull Back (PB)
- Restore Draw (RD)
- Safety Zone (SZ)
- Slash / Burn Pile / Hazard (SBP)
- Staging Area (SA)
- Steep Slope > 35% (SS)
- Stream Crossing (SC)
- Unassigned
- Unique Point (UP)
- Other Rehab Treatment Type
- Pull Back (PB)
- Hazard (H)
- Frequent Machine Completed
- Road - Modified Existing
- Other
- Unassigned
- Rehab - Requires Field Verification
- Rehab - Requires Field Verification
- Fire Perimeter

- Trail
- Trails
- Highway
- Forest Service Road
- Road Permit
- Highway
- Road
- Transmission Lines
- Transmission Line
- Transmission Line
- Mountain
- Stream
- Stream - Intermittent
- Lake
- Lake - Intermittent
- Wetland
- Failing or Gullied Terrain
- Unstable Terrain
- Potentially Unstable Terrain
- Transmission Lines
- Transmission Line
- Transmission Line
- Radio Tower
- Dam
- Archaeological Site
- Water Development
- Fence
- Fish - Observed
- Lake
- Lake - Intermittent
- Private
- Private

Index Map

This map may contain CONFIDENTIAL information; for INTERNAL use only

**Disclaimer:**
Fire perimeters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems on a daily basis. The accuracy of this data is limited to the current fire situation, and therefore should only be used for reference purposes.

Wildfire data from the incident is updated when available. The information is not intended for operational decisions. The information is intended for general purposes only, and should not be used as an accurate measurement tool due to the dynamic nature of the fire change quickly. The levels of current fire activity within the mapped fire perimeters can vary widely.

**Data Sources and Notes:**

**Projection:** NAD 1983 BC Environment Albers
**Created by:** jcarrion

Ministry of Forests, Lands, Natural Resource Operations and Rural Development
BC Wildfire Service

Document Path: Y:\Fire\Seasons\wtr2021\Fuels\qgis\K21849\K21849_Rehab_Zone2_B1.mxd