Tremont Creek
K21849
REHAB MAP
Zone 3 - B2
Map Date: February 21, 2022
Perimeter Date: 2021-08-20
Hectares: 62523.6HA
2 OPS Point [PTType]
PTType
OPS Cleared Area
Hazard
Cross Ditch - Install (CDI)
Decked Wood (DW)
Fence Damage - Point (FD)
Other Rehab Treatment Type
Pull Back (PB)
Restore Draw (RD)
Safety Zone (SZ)
Steep Slope >35% (SS)
Stream Crossing (SC)
Unassigned
Unique Point (UP)
Other Rehab Treatment Type
Pull Back (PB)
Fireguard Machine Completed
Road - Modified Existing
Rehab - Requires Field Verification
Rehab - Requires Field Verification
Fire Perimeter
Trail
Trail
Trail
Trails
Highway
Forest Service Road
Road Permit
Main Road
Road
Pipeline
Pipeline
Pipeline
Transmission Lines
Transmission Line
Transmission Line
Transmission Line
Stream
Stream - Intermittent
Lake
Lake - Intermittent
Wetland
Freshwater
Pipeline
Pipeline
Pipeline
Transmission Line
Failing or Gullied Terrain
Potentially Unstable Terrain
InterpretiveForest/RecreationReserve
O&G Facility
Pipeline
Pipeline
Transmission Lines
Transmission Line
Transmission Line
Transmission Line
Climate Station
Radio Tower
Groudwater Well
Dam
Archaeological Site
Water Development
Fence
Stock Trail
Fish - Observed
Lake
Lake - Intermittent
BC Park, Protected Area, Eco Reserve
Regional & Local Parks
Private
Municipal
Crown Agency
Unknown
Private
Crown Municipal
Index Map
This map may contain CONFIDENTIAL information: for INTERNAL use only
Disclaimer:
Wildfire perimeters for the current fire season, including both active and inactive fires, are supplied from various sources. The data is refreshed from operational systems nightly to the public map. Wildfire data may not reflect the current fire situation, and therefore should only be used for reference purposes.
Wildfire data from the incident is updated when practicable and the occurrence of individual fire updates will vary. The information is intended for general purposes only and should not be relied on as accurate because fires are dynamic and circumstances may change quickly. The limits of current fire activity within the mapped fire perimeters can vary widely.
Data Sources and Notes:
Projection: NAD 1983 BC Environment Albers
Created by: plambkin
BRITISH COLUMBIA
Ministry of Forests, Lands, Natural Resource Operations and Rural Development
BC Wildfire Service
120°50'0"W
120°45'0"W
50°35'0"N
50°30'0"N
TUNKWA PARK
Restore Draw
Track 64
Track 68
Pull Back Berm
Pull Back Berm
Guichon Creek
Forge Creek
Tunkwa Creek
Ware Lake
Chartrand Creek
Axe Creek
MS 462 C-M VW
Corduroy
Decked Wood
Road cave in
Road cave in
Div A Equipment
Decked Wood
Steep Slope
Steep Slope
Steep Slope
Guard Ends @ Wetland
Ditch Blocked - Sewer on Other Side of Rd
Tower
5+ Trees Ripped Up
Ditch Blocked - Clearing send Water Down to House
Could Have Water Problems
Logan Lake
First Aid
Pull Back
Cross Ditch - Install
Pull Back
Pull Back
Pull Back
Pull Back
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Decked Wood
Document Path: Y:\FireSeasonWork\2021\Kamloops\K2\K21849\K21849_Rehab_36x48L.mxd
120°55'0"W